



TOWNSHIP 23 RANGE 09 POINT IDENTIFIER # 500300

PRIMARY CORNER DESCRIPTION Cor Secs 22, 23, 26, & 27

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which the remains of the original bearing trees  
A cedar stump, 54" dia., bears N.2½°E., 43.6 ft., with no marks visible on open blaze. (Record, 46.9 ft.)  
A decayed fir stump, 35" dia., bears S.32°W., 33.7 ft., with axe marks visible on open blaze.  
A decayed fir snag, 39" dia., bears N.52°W., 6.6 ft., with scribe marks 22 visible on open blaze.  
and the remains of the bearing trees mkd. by the Douglas County Surveyor's Office  
A decayed hemlock high stump, 12" dia., bears S.74¾°E., 26.0 ft., with a healed blaze and a nail at the base on the left side center.  
A hemlock, 27" dia., bears S.83½°W., 25.6 ft., no marks visible. Add scribe marks T23S R9W S27 BT and a Mag Nail at the base on the right side center.  
and new bearing trees  
A fir, 17" dia., bears N.33°E., 22.4, mkd. T23S R9W S23 BT  
A hemlock, 8" dia., bears S.82¾°E., 20.4, mkd. T23S R9W S26 BT.  
A hemlock, 9" dia. bears N.30°W. 9.3, mkd. T23S R9W S22 BT  
Drive an aluminum angle iron alongside the cor.