

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 22 & 23

Alias	Description

GLO survey by Oscar F. Thiel, under contract # 688, dated June 9, 1898 - (DCSO records Vol. 7 Page(s) 2673)

Set a sandstone, 16x12x6", 11" in the ground for ¼ sec. cor. mkd: ¼ on W. face, raised a mound of stone around it; from which:
 A Fir, 36" dia., bears N.10°E., 14 lks., mkd: ¼ S23 BT.
 A Fir, 30" dia., bears S.21°W., 14 lks., mkd: ¼ S22 BT.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy Co. Surveyor - Wm Stoffel - Mike Stone - Oct. 1964 - C.S. 53/84-1

Found - Mound of rocks - one rock mkd: "4"
 36" Fir N.10°E., 9.2 ft., from face, very plain axe scar.
Set - Brass cap at cor. mkd: COUNTY SURVEYORS OFFICE 1964
 T23S R9S ¼ S 22|S 23
 Both BTs are in good condition, scars plain. Did not rescribe.
Note - Corner is approx. 50 ft. North of ridge top and 50 ft. West of ridge top.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - E. West - March & April 1967 - C.S. File 54/60-1

Found - 1962 Co. Surveyor brass cap properly mkd. & rec. in 1964
 Fragments of orig. sandstone corner rock used to fill hole for brass cap.
 Orig. 36" now 48" Fir, N.10°E., 9.2 ft. from face, alive, unopened. Shows good scar.
 Orig. 30" now 34" Fir, S.21°W., 9.2 ft. from face, alive, unopened. Shows good scar.
New BTs- 8" Hemlock S.70°W., 16.7 ft., mkd: ¼ S22 CS BT
 11" Hemlock S.72°E., 13.4 ft., mkd: ¼ S23 CS BT
Note - This corner lies 25 ft. W & 35 ft. N of top of main ridge, course NE - SW.
*(rec. 1964, 6/28/1999)

BLM Dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2756, surveyed May 2014 - (DCSO records Vol. 58 Page(s) 23304-5)

The ¼ sec. cor. of secs. 22 & 23, perpetuated by the Douglas Co. Surveyor's Office in 1964 and again in 1967; monumented with an iron post, 1" dia., firmly set, projecting 4" above ground, with a brass cap (properly) mkd.
continued next page

TOWNSHIP 23 RANGE 09 POINT IDENTIFIER # 500340

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 22 & 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which the original bearing trees
A fir, 58" dia., bears N.10°E., 12.2 ft., with a healed blaze. (Record, 9.2 ft.)
A fir, 35" dia., bears S.21°W., 9.2 ft., with a healed blaze.
and the bearing trees mkd. by the Douglas County Surveyor's Office in 1967
A hemlock, 23" dia., bears S.73½°E., 13.5 ft., with a healed blaze.
A hemlock, 13" dia., bears S.69°W., 16.7 ft., with a healed blaze.
Drive an aluminum angle iron alongside the cor.
From the corner
S.45°W., 15 ft., ridge, bears N.30°E. and S.30°W.