

TOWNSHIP 23 RANGE 09 POINT IDENTIFIER # 600600

PRIMARY CORNER DESCRIPTION Cor Secs 1, 2, 11, & 12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars under contract #279, dated March 5, 1878 - (DCSO records Vol. 6 Page(s) 2619)

Set post, a Fir, 4" dia., 4 ft. long, 20" in the ground for the corner to secs. 1, 2, 11, & 12, from which

- A Fir, 14" dia., bears N.22°E., 68 lks.
- A Hemlock, 8" dia., bears S.45°E., 20 lks.
- A Fir, 12" dia., bears S.50°W., 56 lks.
- A Fir, 8" dia., bears N.70°W., 33 lks.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy & crew - Feb. 1968 - C.S. File 54/60-39

Found - 4x4x48" sq. post scribed & set for cor. We find NO TRACE OF ORIG. BTS unrecorded BTs as follows:

- 22" D.Fir S.25°E., 24.7 ft. (face) bark scribed: MRP 24.7
- 22" D.Fir S.87°E., 48.7 ft. (face) bark scribed: RP 48.7
- 26" D.Fir N.13°W., 29.1 ft. (face) bark scribed: RP 29.1. poor
- 32" D.Fir, stump, S.61°W., 30.5 ft., (face) bark scribed: RP 30.5.

We used numbers in bark scribes for distances from BT & took bearings from that point. Post was tipped out.

Douglas Co. Surveyors Office - Larry E. Monrean - Pete Earle - 10/1973 - C.S. File 56/39-15

Unrecorded evidence found. Corner not set

Found - Wood post 4"x3'; out of ground with scribing.

- 30" Fir, scribed "R P S1" tagged with BLM BT tag, reads as follows: Cor. is approx. 28 ft. S.8°E., T23S R9W Sec. 2. Posted by P.A.S. Ap 71
- 30" Fir, scribed "? MRP 2.2 ft. tagged w/BLM BT tag which reads as follows: Cor. is approx.. 24.7 ft. N.25°W., T23S R9W Sec. 12 posted by PAS Apr. 71.

Also find -

- 36" Fir stump, bears S.63°W., 30 ft., scribed "RP 3 5". Could possibly be orig. SW BT old scribe would be lost due to new scribing.

No sign of other BTs. See also C.S. File 54/60 (report above)

continued next page

1

TOWNSHIP 23 RANGE 09 POINT IDENTIFIER # 600600

PRIMARY CORNER DESCRIPTION Cor. Secs. 1, 2, 11, & 12

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM dependent resurvey by Harvey E. Wofford & Stephen J. Malloy, Cadastral Surveyors, under Group #1005, surveyed July 1980 - Nov. 1982 - (DCSO records Vol. 43 Page(s) 16856)

From the cor. of secs. 1, 2, 11 & 12, monumented with a 5 ft. steel fence post, firmly set, 24" in the ground, from which the remains of an orig. BT:

A Fir stump, 36" dia., bears S.50°W., 58 lks., with fragmentary scribe marks visible on burned & decayed bark blaze, and remarked RP3 on bark blaze by person(s) unknown.

and local BTs mkd. by person(s) unknown

A Fir, 30" bears S.17¼°E., 50 lks., with scribe marks RP 51 visible on bark blaze.

A Fir 30" dia., bears N.20¼°W., 34 lks., with scribe marks RP2 visible on bark blaze.

At the corner point

Set an iron post, 28" long, 2½" dia., 26" in the ground, with brass cap marked:

T23S	R9W
S 2 S 3	
S 11 S 12	
1980	

from which

A Fir, 8" dia., bears N.78½°E., 50 lks., mkd: T23S R9W S1 BT.

A Fir, 8" dia., bears S.41 3/4°W., 107 lks., mkd: T23S R9W S11 BT.

Reset the fence post alongside the iron post.

Fd. Ok by Mark Smalley - 10/1997 - M 124-64