TOWNSHIP 23 RANGE 09 POINT IDENTIFIER # 700158

PRIMARY CORNER DESCRIPTION W. 1/4 Cor. for Sec. 31 only, T23-8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2544)

Set a post 3 ft. and 3" sq., 2 ft. in ground for ¼ sec. cor. marked ¼ S on W. face, from which
A Fir 70" dia. bears N.2°E., 70 lks. dist. mkd. ¼ S BT.
A Hemlock 6" dia., bears S.38°E., 7 lks. dist. mkd. ¼ S BT

Douglas Co. Surveyors Office - Clell Goodwin; Mary L. Ladig, crew - June 10, 1975 - C.S. File 57/30-7

Found - Rotted Hemlock stump with scribed "BT" legible, bears S.38°E., 4.6 ft. Scribe is on NE. face of stump.
70" Fir with scar, bears N.62°E., 46.2 ft. (Call N.2°E., 46.2 ft.)
I intersect call distances and match bearing to SE. BT (No sign of any other possible 70" Fir) and
Set brass cap on 1½" Iron pipe, stamped: Douglas Co. Surveyor



New BT - 8" Hemlock scribed "T23S R8W S31 CS BT" in a double blaze, bears S.63°E., 14.7 ft.