

PRIMARY CORNER DESCRIPTION West 1/4 Cor. for Sec. 7 only, T23-8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2548-49)

Set a post 3 ft. long and 3" sq., 2 ft. in ground for ¼ sec. cor., marked ¼ S on West face, from which
A Fir 36" dia., bears S.62°W., 25 lks. dist. mkd. ¼ S BT
A Hemlock 4" dia., bears S.25°E., 2 lks. dist. mkd. ¼ S BT

BLM Resurvey by Harvey E. Wofford and Stephen J. Malloy, Cadastral Surveyors, under Group #1074, Surveyed July 1980/Nov. 1982 - (DCSO records Vol. 43 Page(s) 16848-49)

True point for the ¼ sec. cor. of sec. 7 only, T23S R8W.
Set an iron post 28" long, 2½" dia., 24" in the ground, with brass cap mkd:
T 23 S
R 9 W R 8 W
1/4 S 7
1980

from which new bearing trees;
A Fir 9" dia., bears N.46°E., 31½ lks. dist., mkd. X BT.
A Fir 16" dia., bears S.24°E., 32 lks. dist., mkd. ¼ S7 BT.

From this point, the original ¼ sec. cor. of sec. 7 only, bears West, 0.12 chs. dist., monumented with a steel fence post, firmly set, projecting 36" above ground from which the remains of the original bearing trees:
A roothole bears S.62°W., 25 lks. dist., alongside of which is a downed Fir 48" dia., with scribe mark S visible on opened blaze.

Mark Smalley - For: Riverbend Resources - Oct. 1997 - M 124-64

Found - 1980 Cadastral Brass Cap on iron pipe.
23" Fir, S.26°E., 21.3', 21.3', (S.24°E., 21.1' - 1980) healed.
13" Fir, N.52°E., 20.8', (N.46°E., - 1980) healed.
Root hole bears S.62°W. 16.5', down fir, 48" alongside.
New BTs- 12" Fir, S.28°W., 34.2', scribed "¼ S7 BT"
11" Fir, N.32°W., 21.1', scribed "¼ S7 BT"
Note - Steel post marking orig. corner bears, West 7.7' (7.9' - 1980)