

PRIMARY CORNER DESCRIPTION E. 1/4 cor. for Sec. 12 only

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by - William H. Byars, Deputy Surveyor, Under Contract No. 279, dated March. 5, 1878 - (DCSO records Vol. 6 Page(s) 2537)

-----  
Set a Fir post 4" dia., 4 ft. long, 18" in ground for ¼ sec. corner, from which

- A Fir 8" dia., bears S.30°E., 18 lks. dist.
- A Fir 6" dia., bears N.70°W., 5 lks. dist.

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2549)

-----  
The old ¼ sec. cor. on E. bdy. of Sec. 12, T23S R8W. The post being gone and the BTs greatly decayed, I reestablished the corner by setting a post 3 ft. long, and 3" sq., 2 ft. in the ground marked ¼ S on W. face, from which

- A Fir 24" dia., bears N.48°E., 21 lks. dist. which I marked ¼ S BT.
- A Fir 10" dia., bears S.52°W., 45 lks. dist. which I marked ¼ S BT.

BLM Resurvey by Harvey E. Wofford and Stephen J. Malloy, Cadastral Surveyors, under Group #1074, Surveyed July 1980/Nov. 1982 - (DCSO records Vol. 43 Page(s) 16849)

-----  
Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd:

T 23 S  
R 9 W R 8 W  
1/4 S 12  
1980

from which

- A Fir 11" dia., bears S.56 ¾°W., 50 lks. dist. mkd. X BT
- A Fir 14" dia., bears N.42 ¾°W., 21 lks. dist. mkd. ¼ S12 BT.

Mark Smalley - For: Riverbend Resources - Oct. 1997 - M 124-64

-----  
Found - 1980 Cadastral Brass cap on iron pipe.

- 18" Fir, S.56 ¾°W. 33.0' healed.
- 21" Fir, N.42 ¾°W., 13.9', healed.
- New BTs- 20" Fir, S.56°E., 45.1', scribed "¼ S12 BT"
- 22" Fir, N.24°E., 10.2', scribed "¼ S12 BT"