

TOWNSHIP 23 RANGE 10 POINT IDENTIFIER # 400100

PRIMARY CORNER DESCRIPTION C C for Secs. 33 & 34 only (South)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Levi C. Walker, Deputy Surveyor, under Contract #763, dated June 20, 1905 - (DCS0 records Vol. 7 Page(s) 2724)

-----  
Set a Hemlock post, 3 ft. long, 4" sq., 24" in the ground for C C of secs. 33 and 34, marked CC T23S R10W on N.; S34 on E.; and S33 on W. face, with 3 grooves on E. and W. faces, from which  
A Fir 30" dia., bears N.6°E., 29 lks. dist. mkd. T23S R10W S34 BT.  
A Fir 16" dia., bears N.73°W., 66 lks. dist. mkd. T23S R10W S33 BT.

Oregon State Board of Forestry - 1933 (Filed April 24, 1958)  
C.S. File 49/80-1 pg 7

-----  
4" x 5" Hemlock post, replacing post set by Levi Walker, 436.9 ft. East of closing cor. for secs. 3 & 4.  
Found decayed post and BTs:  
30" Fir N.6°E., 19 ft. (old BT)  
16" Fir N.73°W., 43 ft. (old BT)  
New BTs- 24" Fir N.10°W., 15 ft.  
18" Fir S.62°W., 22 ft.

Arnold G. Gibson - For: OSBF - April 27, 1960 - C.S. File 42/422-4

-----  
Resurvey by Levi Walker in 1905:  
Hemlock post, now missing, from which  
30" Fir bears N.6°E., 29 lks.; now 30" windfall scribed S34 T23 R10W BT on exposed face.  
16" Fir bears N.73°W., 66 lks.; now 18" snag, scribed 33 BT on exposed face.  
Restoration by Elliott Survey of 1936:  
4" x 5" Hemlock post, found, not in place, from which a 24" Fir bears N.10°W., 15 ft.; (orig. 30" BT)  
18" Fir bears S.62°W., 22 ft.; now 24", bearing S.76°W., 24.2 ft. scribed 33 in exposed face.  
Set 1½" x 36" galv. I.P. with 3' bronze cap mkd. "Ore. St. Bd. of Forestry CC T23S R10W S33 S34 S3 T24S R10W 1960 RS359", 33" in ground in mound of stone, and from which  
48" Fir bears N.38°E., 29.6 ft. scribed CC T23S R10W S34 RS 359 BT.  
32" Fir, N.18½°W., 28.9 ft. scribed CC S33 T23S R10W BT.  
OSBF metal location poster on 18" Fir BT.  
Set 4"x4"x6 ft. wh. painted Cedar post 1.5 ft. S. of pipe.

(Cont. Next Page)

TOWNSHIP 23 RANGE 10 POINT IDENTIFIER # 400100

PRIMARY CORNER DESCRIPTION C C for Secs. 33 and 34 only (South)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Arnold G. Gibson - Oregon Dept. of Forestry - Aug. 23, 1960  
-C.S. File 42/422-7 and C.S. 49/80 & survey filed in Coos Co.  
rec'd 2015 C.S. File 65/91-2

-----  
Set 1½" x 36" I.P. with 3" bronze cap mkd. "Ore. St. Bd. of  
Forestry T23S R10W CC S33 S34 S3 T24S R10W 1960 RS 359", 30"  
in ground, S.0°31'E., 3.7 ft. from original CC which I mark  
AM on the pipe cap and AM on each of the bearing trees.

Tony Hostetter - For: Weyerhaeuser Co. - May 27, 2015 - C.S.  
File 65/89-47

-----  
Found - ¾" iron pipe (no evidence of board of Forestry brass  
cap as described by Gibson, C.S. File 42/422)  
48" fir stump, scribing visible, WEYCO tag, "W"  
nail, bears N.38°E., 29.6 ft. to center.  
24" fir stump, OSBF tag, "W" nail, bears S.76°W.,  
24.2 ft. to center.  
New BTs- 15" fir, BT tag, bears N.25°E., 7.8 ft. to 6" spike,  
placed below tag.  
18" Fir, BT tag, bears S.20°E., 12.6 ft to 6" spike,  
placed below tag.  
12" Fir, BT tag, bears N.84°W., 26.2 ft to 6" spike,  
placed below tag.

Please note that this corner is on the Douglas Co. & Coos Co.  
line and Coos Co. Surveyor's Office may have more information  
concerning this corner.