

TOWNSHIP 23 RANGE 10 POINT IDENTIFIER # 500100

PRIMARY CORNER DESCRIPTION Standard Cor. for Secs. 34 & 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by - William H. Byars, Deputy Surveyor, Under Contract No. 292, dated Aug. 7, 1878 - (DCSO records Vol. 7 Page(s) 2700)

-----  
Set a Yew post 5 ft. long, 5" dia., 20" in the ground for the corner to secs. 2, 3, 34 and 35, from which  
A Fir 36" dia., bears N.15°E., 37 lks. dist.  
A Fir 20" dia., bears S.58°E., 17 lks. dist.  
A Fir 20" dia., bears S.61°W., 24 lks. dist.  
A Fir 30" dia., bears N.3°W., 42 lks. dist.

Fd. and tied in GL0 survey by Levi C Walker, Deputy Surveyor, under Contract #763, dated June 20, 1905 - (DCSO records Vol. 7 Page(s) 2722)

Donald L. Peel - For: Weyerhaeuser Co. - March 1967 - C.S. File 55/30-1

-----  
Found - GL0 survey record, post gone.  
36" Fir N.15°E., 37 lks.; now 30" Fir stump, nothing visible, probably bark scribing.  
20" Fir S.58°E., 17 lks., markings destroyed in 1896,; now 26" Fir snag, face visible.  
20" Fir S.61°W., 24 lks.; markings visible in 1896, now 32" Fir, face visible.  
30" Fir N.3°W., 42 lks.; now Fir snag, face visible, chopped open, but rotted from inside, no scribing left.  
Set 3/4" x 4 ft. pipe, 3 1/2 ft. into the ground for corner and re-referenced with "W" nails and Weyerhaeuser tags:  
10" hemlock N.10°E., 19.8 ft.  
24" Hemlock N.80°W., 23.4 ft.

Fd. OK, July 31, 1973 by DCSO - C.S. File 56/35-5

Douglas Co. Surveyors Office - Clell Goodwin and Lenora Ladig, crew - June 17, 1975 - C.S. File 57/30-18

-----  
Found 3/4" pipe set by Weyerhaeuser and remains of all original BTs.  
Set 1 1/2" Iron pipe flanged on bottom, projecting 1 ft. out of ground, from which a  
10" Hemlock bears N.10°E., 21.2 ft. scribed "S35 X" in single blaze.  
24" Hemlock bears N.80°W., 24.4 ft. scribed "X S34".

continued next page

TOWNSHIP 23 RANGE 10 POINT IDENTIFIER # 500100

PRIMARY CORNER DESCRIPTION Standard Cor. for Secs. 34 & 35

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Tony Hostetter - For: Weyerhaeuser - April 2019 - C.S. File 65/103-7

-----  
Found - 1½" iron pipe as set by DC Surveyors Office in 1975 (C.S. 57/30) from which:  
24" hemlock stump, tag and face evident, bears; N.10°E, 21.2 ft, to "W" center.  
New BTs- 12" hemlock, marked "X", BT tag, S.78°E., 10.1 ft to spike.  
20" Hemlock, marked "X", BT tag, S.42°E., 20.5 ft to spike.  
12" Hemlock, marked "X", BT tag, N.73°E., 8.2 ft to spike.

Jerry Estabrook - Crew: Blue James, Jack Jarrett & Daniel Tlemissen - 12/15/2020 - C.S. 65/109-6

-----  
Conditional report only  
Found - A 1½" iron pipe, per CS 57/30-18.  
A 24" Hemlock live tree (record states stump) with healed face and tag bears N.10°E., 21.2'.  
A 12" Hemlock with x-chop, tag and spike in face bears S.78°E., 10.1'.  
A 20" Hemlock with x-chop tag and spike in face bears S.42°W., 20.5 (Record S.42°E.).  
A 12" Hemlock with x-chop, tag and spike in face bears N.73°W., 8.2' (Record N.73°E.).  
A steel fence post bears East 0.7'.  
Locations & Comments -  
LAT. and LONG. per GARMIN ETREX hand held GPS  
N: 43°30'58.3" W:123°51'19.1"  
Note - Compass Declination 18° EAST