

PRIMARY CORNER DESCRIPTION 1/4 Sec. 14 only, (west)

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

GL0 survey by W.H. Byars under contract #292, dated August 7, 1878 - (DCSO records Vol. 7 Page(s) 2713)  
-----  
Set a Fir post, 5 ft. long, 5 ins. dia., 20" in ground for the ¼ sec. cor. between secs. 14 & 15, from which  
    A Fir, 8" dia., bears S.5°E., 84 lks.  
    A Fir, 8" dia., bears S.2°W., 109 lks.

GL0 resurvey and retracement by Levi C. Walker under contract #763, dated Aug. 23, 1905 - (DCSO records Vol. 7 Page(s) 2753)  
-----  
I make diligent search for the ¼ cor. but can find no trace of it.  
Set a Fir post 3 ft. long, 4" sq., 24" in the ground, fro ¼ sec. cor., marked ¼ S on W & 14 on E face, from which  
    A Fir, 12" dia., bears S.77°E., 23 lks., mkd: ¼ S14 BT.  
    A Fir, 10" dia., bears N.80°W., 44 lks., mkd: ¼ S BT.

Arnold G. Gibson, Oregon St. Board of Forestry - George Shore, Transitman - 1/15/1959 filed 1/28/1960 - C.S. File 42/422-2  
-----  
Found - Orig. post, now missing from which a:  
    8" Fir bears S.5°E., 84 lks., now missing.  
    8" Fir bears S.2°W., 109 lks., now missing.  
Retracement by Levi C. Walker, June 1905  
    Post now missing, from which a  
    12" Fir bears S.77°E., 23 lks., now 31", face exposed by unknown party, face rotted, orig. axe work visible.  
    10" Fir bears N.80°W., 44 lks., now 27"x6' stub, face exposed by unknown party, orig. axe work visible on small portion of face on down log, most of face destroyed when tree blew down.  
Summit of divide, South 37 lks., now in place.  
Set - 1½"x36" galv. IP with 3" bronze cap mkd: "Ore. St. Bd. of Forestry ¼ S14 1959 RS359", 33" in ground in mound of stone, and from which a:  
    30" Fir bears S.60°E., 36.9 ft., scribed ¼ S14 359.  
    20" Fir bears N.57½°E., 50.1 ft., scribed ¼ S BT  
Oregon T. Bd. of Forestry metal location poster on  
    16" Fir S.88°W., 40.2 ft.  
    4"x4"x72" white painted Cedar post 1.5 ft. NW of pipe.

TOWNSHIP 23 RANGE 10 POINT IDENTIFIER # 500440

PRIMARY CORNER DESCRIPTION 1/4 Sec. 14 only, (west)

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

James M McIntosh - For: Oregon Dept. Of Forestry - March 1999  
- M 131-44

-----  
Found - Oregon St. Board of Forestry 1½" x 36" galv.  
IP/3" bronze cap, 1959  
12" Fir (1906) S.77°E., 23 lks., now windfall  
downhill, face exposed & badly decayed, no  
scribes visible.  
10" Fir (1906) N.80°W., 44 lks., now 23"x 5' high  
rotten stub in place exposed, no scribes  
visible.  
Summit of divided South 37 lks.  
30" Fir (1959) S.60°E., 36.9 ft., now 45" x 2' high  
stump face closed.  
20" Fir (1959) N.57½°E. 50.1 ft, now 28" face closed  
16" Fir (1959) S.88°W., 40.2 ft., yellow metal  
location poster only, now 16"x3' high rotten  
stub, yellow metal location poster fallen off.  
White painted cedar post NW 1.5 ft. now rotten and  
fallen over.  
Set - 16" Fir S.56°E., 32.4 ft., to aluminum nail in BT  
face scribed: ¼S14BT. Bearing tree tag.  
Orange Carsonite markers CBM-250R labeled WP bears:  
S.76°E., 3.40 ft. to base.  
N.23°E., 2.40 ft. to base.