

PRIMARY CORNER DESCRIPTION Cor. Secs. 11, 14, & 15 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars under contract #292, dated August 7, 1878 - (DCSO records Vol. 7 Page(s) 2713-14)

Set a Fir post, 5 ft. long, 5 ins. dia., 20" in the ground for the corner to secs. 10, 11, 14 & 15, from which
A Fir, 10" dia., bears N.23°E., 95 lks.
A Fir, 50" dia., bears S.45°E., 72 lks.
A Fir, 20" dia., bears S.75°W., 54 lks.
A Fir, 8" dia., bears N.15°W., 131 lks.

GLO resurvey and retracement by Levi C. Walker under contract #763, dated Aug. 23, 1905 - (DCSO records Vol. 7 Page(s) 2734)

The post set for the cor. of secs. 10, 11, 14, & 15 being much decayed, I destroy, and at the same point, Set a Fir post, 3 ft. long, 4" sq., 24" in the ground, for the cor. of secs. 11 & 14, marked T23S S11 on NE, R10W S14 on SE., S15 on SW & S15 on NW face, with 4 notches on S & 2 notches on E. edge.
I obliterate all marks upon the BTs referring to secs. 10 & 15.
In place of BT in sec. 14, only the stump of which remains I mark the following:
A Fir, 6" dia., bears S.11½°E., 75 lks., mkd: T23S R10W S14 BT.

Arnold G. Gibson, Oregon St. Board of Forestry - Dec. 8, 1972 - M 49-20

Sec. Cor. reestablished
Set - OSBF iron pipe with 3" bronze cap, 34" in ground.
9" Fir N.77°E., 23.5 ft. with yellow metal location poster.
10" Fir s.28½°E., 44.0 ft. (RS359)
4"x4"x72" white painted Cedar post N.80°E., 2.8 ft.

Arnold G. Gibson, St. of Oregon, Dept. of Forestry - Witnessed by James M. McIntosh - June 14, 1976 - C.S. File 58/31

No evidence of orig. corner found.
Restoration by A. Gibson, 1972
Found - 1½"x36" GIP, in place, from which a:
9" Fir bears N.77°E., 23.5 ft., missing in new road location.
10" Fir s.28½°E., 44.0 ft., missing in new road location.
continued next page

TOWNSHIP 23 RANGE 10 POINT IDENTIFIER # 500500

PRIMARY CORNER DESCRIPTION Cor. Secs. 11, 14, & 15 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

4"x4"x72" white painted Cedar post N.80°E., 2.8 ft.,
found in place.
Re-witnessed from above 1½"x36" GIP. a:
14" Fir bears S.1°W., 111.9 ft. to face, scribed
T23S R10W S14 BT RS 359
15" Fir stump bears S.31°E., 108.5 to face, scribed
T23S E10W S14 BT RS 359
Oregon St. Forestry Dept. metal location poster on
4"x4"x72" WPCP N.80°E., 2.8 ft.

Oregon Dept. of Forestry, James McIntosh - Witness: Ralph C.
Hall - Sept. 26, 2000 - C.S. File 65/33-4

Found - Oregon State Board of Forestry 1½"x36" galvanized
iron pipe with 3" bronze cap. 1972
1972 fir trees missing, in road.
4"x4"x72" white painted cedar post N.80°E., 2.8 ft.,
in place. 1972
14" Fir S.1°W., 111.9 ft., now 21" in place, face
closed. 1976
15" Fir stump S.31°E., 108.5 ft., now 12"x2' high
rotted stump in place, no marks visible.

Rewitnessed from the above pipe & cap -
11" Fir N.57°E., 8.6' to alum. nail in BT face
scribed T23S R10W S11 BT. BT tag.
Carsonite witness post N.84°E., 3.7' to base.
Carsonite witness post S.28°E., 3.6' to base.
10" Fir S.10°E., 26.7' to alum. nail in BT face
scribed T23S R10W S14 BT. BT tag.
Added BT tag on White painted cedar post.

Note - Magnetic variation set at 20°E.