

TOWNSHIP 23 RANGE 10 POINT IDENTIFIER # 600540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 11 & 12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by W.H. Byars under contract #292, dated August 7, 1878 - (DCSO records Vol. 7 Page(s) 2707)

Set a Laurel post, 5 ft. long, 5 ins. dia., 18" in ground for the 1/4 sec. cor. between secs. 11 & 12, from which
 A Fir, 8" dia., bears S.25°E., 33 lks.
 A Fir, 10" dia., bears S.50°W., 25 lks.

GL0 survey by Levi C. Walker under contract #763, dated Aug. 23, 1905 - (DCSO records Vol. 7 Page(s) 2755 & 2757)

Pg. 2755
I make diligent search for the 1/4 sec. cor. but can find no trace of it.
Page 2757
Set a Cedar post, 3 ft. long, 5 ins. dia., 24" in ground for the 1/4 sec. cor. between secs. 11 & 12, marked 1/4 sec. 11 on W. and 12 on E face, from which
 A Fir, 20" dia., bears N.69°E., 31 lks., mkd: 1/4 S12 BT.
 A Fir, 24" dia., bears S.17°W., 54 lks., mkd: 1/4 S11 BT.

Elliott State Forest Corner Records by Federal Civilian Conservation Corp (CCC) 8/1933 - FB 119 Pg. 51 (Filed 4/24/1958 C.S. File 49/80)

Found 1/4 post which was partially rotted & one BT.
 Replaced post with 4"x4"x4' Red Cedar Post.
 30" Fir N.70°E., 20 ft. - 0BT
 12" Fir N.78°W., 8 ft.

Douglas Co. Surveyors Office - James W. Byron, Deputy - Milo Godfrey - S.A. Bilow - For: Mr. Rose & Mr. Lee "West Shore Lodges" - Feb. - May 1958 - C.S. File 49/90 (pg 6) & M8-72

Found - 4"x4" stake at corner & orig. Fir, now 39", has open face some scribing visible. I bark scribe this BT
Set - Brass cap at corner mkd: 1/4 S11/S12 T23S R10W County Surveyors Office, 1958
 10" Hemlock bears S.1 1/2°E., 19.7 ft. scribed 1/4 S12 CS BT.