

TOWNSHIP 24 RANGE 01 POINT IDENTIFIER # 100444

PRIMARY CORNER DESCRIPTION E. 1/4 Cor. for Sec. 13 only, T24-2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 7 Page(s) 2876) and duplicate Page 2764)

Set Cedar post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor. mkd. ¼ S. on W. face, from which

A Chinquapin 16" dia., bears S.61°E., 14 lks. dist. mkd. ¼ S BT.

A Laurel 5" dia., bears N.55°W., 6 lks. dist. mkd. ¼ S BT.

GLO survey by Carl S. Nicklin, Deputy Surveyor, under joint contract #664 dated May 23, 1896 (DCSO records Vol. 7 Page(s) 2941)

Make diligent search for ¼ sec. cor., but fail to find any trace thereof.

Not Fd - DCSO, VRT Sept 1969 - C.S. file 54/27-256 - find no trace of ¼ - we cannot find line trees close to ¼ cor. or any bluff just north of it.