

TOWNSHIP 24 RANGE 01 POINT IDENTIFIER # 140600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 6 & 7

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Carl S. Nicklin, Dep. Surveyor under contract # 664, dated May 23, 1896 - (DCSO recs Vol. 7 Page(s) 2861)

Set a fir post, 4 ft. long, 4" sq., 24" in the ground, for 1/4 sec. cor. marked 1/4 S on N face, from which

A fir, 6" dia., bears N.28°E., 36 lks., mkd: 1/4 S BT.

A hemlock, 30" dia., bears S.43°E., 14 lks., mkd: 1/4 S BT.
This cor. is on a hillside, sloping NE about 250 ft. below ridge.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - V. Perron - May 1970 - C.S. File 54/27-187

Found - Orig. 6" now 10" Fir, broken off near ground, N.28°E., 23.8 ft. find "1/4S" scribe on log.
Orig. 30" now 36" Hemlock, alive, S.43°E., 9.2 ft., blaze open, scribe visible.

Set - Brass cap at cor. mkd: County Surveyors T24S R1W
Office 1970 1/4 S 6
S 7

New BTs- 14" Fir N.27 1/2°E., 31.3 ft., mkd: "1/4 S6 CS BT"

11" Hemlock S.50°E., 41.8 ft., mkd: "1/4 S7 CS BT"

This corner lies on steep NE slope about 300 ft. N of top of Calapooya Divide.