

PRIMARY CORNER DESCRIPTION Sec Cor for 31 & 32; 5 & 6, T25-1

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

GLO survey by Carl S. Nicklin, Deputy Surveyor, under joint contract #664 dated May 23, 1896 (DCSO records Vol 7 Pg 2777)

 Set a Yew post 4 ft. long, 4" sq., 24" in the ground for cor. of secs. 32, 5, 6 and 31, marked T24S S32 on NE.; R1W S5 on SE.; T25S S6 on SW.; and S31 on NW. faces; with 1 notch on W. and 5 notches on E. edges, from which

A Hemlock 10" dia., bears N.63°E., 22 lks. dist. mkd. T24S R1W S32 BT.

A Hemlock 10" dia., bears S.55°E., 9 lks. dist. mkd. T25S R1W S5 BT.

A Fir 12" dia., bears S.87½°W., 70 lks. dist. mkd. T25S R1W S6 BT.

A Cedar 14" dia., bears N.59°W., 62 lks. dist. mkd. T24S R1W S31 BT.

Cor. is on a steep hillside, sloping E. about 25 ft. below top of ridge.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Nov. 30, 1966 - C.S. File 52/30-69

 Found - Orig. 12" now 17" Fir stump, S.87½°W., 46.2 ft. We open and find "S6 R1W" scribe and reverse. Brg. & approx. dist. fit holes of other original bearing trees, down an out of position.

Set Brass cap at cor. mkd: County Surveyors Office

T	24	S	R	1	W
	S	31	S	32	
	S	6	S	5	
					1966

New BTs- 6" Hemlock N.73°W., 52.0 ft. mkd. T24S R1W S31 CS BT

12" Yew S.66½°W., 16.8 ft. mkd. T25S R1W S6 CS BT.

11" Yew S.25°E., 24.4 ft. mkd. T25S R1W S5 CS BT.

8" Hemlock N.29°E., 59.8 ft. mkd. T24S R1W S32 CS BT

Corner lies on NE. slope in logged unit.

Corner Fd. and Used in BLM resurvey by James E. Jelley, Cadastral Surveyor - under Group #1061, surveyed April/June 1981 - (DCSO records Vol. 45 Page(s) 17354-55)

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2500, Surveyed Sept./Nov. 2011 - (DCSO records BLM Plat T25-1W 2012-2 & Vol. 58 Pages 22945-6)

 The cor. of secs. 5, 6, 31 & 32, on the N bdy of the Tp. monumented with an iron post, 1¼" dia., firmly set, projecting 8" above ground, with brass cap (properly) mkd.
 continued next page

PRIMARY CORNER DESCRIPTION Sec Cor for 5 & 6; 31 & 32, T24-1

Alias	Description
Alias	Description
Alias	Description
Alias	Description

from which the remains of orig. BTs
A roothole bears N.63°E., 14.5 ft., downhill of which is a fallen, decayed, hemlock snag, size indeterminate, with no marks visible.
A roothole bears S.55°E., 5.9 ft., downhill of which is a fallen, decayed, hemlock snag, size indeterminate, with no marks visible.
A sawed fir stump, 18" dia., bears S.85°W., 46.2 ft. with scribe marks R W and other fragmentary scribe marks visible on an open blaze (Rec. S.87½°W)
A roothole bears N.59°W., 40.9 ft., downhill of which is an uprooted, decayed cedar stump, size indeterminate, with no marks visible.
and BTs mkd by Douglas Co. Surveyor's Office in 1966
A hemlock, 20" dia., bears N.27°E., 59.7 ft., with a healed double blaze.
A yew, 14" dia., bears S.27°E., 23.8 ft., with scribe marks T25S R1W S5 CS BT visible on a partially healed blaze.
A yew, 12" dia., bears S.64°W., 16.8 ft., with scribe marks T25S R1W S6 CS BT visible on a partially healed blaze.
A hemlock, 22" dia., bears N.73°W., 52.1 ft., with a healed double blaze.
Corner is located 380 ft. W of a graveled road, 12 ft. wide, bears N.70°W., and S.70°E.

Gerald Nygren - For: Barnes & Associates - 12/2018 - M175-10

Found - 1966 County Surveyor brass cap per rec.
12" Fir, now rotten stump bears S.85°W., 46.2' healed blaze (1896)
8" Hemlock, now 21" bears N.27°E., 59.7' healed blaze (1966)
11" Yew, now 14" snag bears S.27°E., 23.8' visible scribe.
12" yew, now 12" snag bears S.64°W., 16.8' visible scribe.
6" Hemlock, now 23" bears N.73°W. 52.1' healed blaze
Set - 5' galv. Metal post 1.0' west.