

| Alias | Description |
|-------|-------------|
| _____ | _____ |
| _____ | _____ |
| _____ | _____ |
| _____ | _____ |

Orig. 8" fir, now 8' dia., 4 ft. high stump bears S.17°W., 8.5 ft. (rec. S.26°W., 8.6 ft) scribing legible (24 S R1W S31 BT)
Orig. 8" fir now 2 stumps are close to bearing & dist. (rec. N.83°W., 19.8 ft.)
12" fir, now 12" fir, bears N.29°E., 53.0 ft. Double blaze nearly healed. 1960
18" Fir now 15" dia., snag, 15 ft. high, bears S.81°W., 22.3 ft. Partially healed blaze, scribing visible.
8" fir destroyed.
New - 9" fir, double blazed & scribed "T24S R1W S29 CS BT" bears N.83°E., 57.2 ft.
14" Fir, double blazed & scribed "T24S R1W S31 CS BT" bears S.22°W., 42.0 ft.
Set a 8"x1/2" spike in a 18" fir stump, bears N.86°W., 19.1 ft. Spike set through a "DOUGLAS CO SURVEYORS OFFICE" BT tag in center of stump (stump is possible orig. 8" fir BT)
Note - Cor. lies on steep NW'ly slope approx. 200 ft. easterly of the end of BLM rd. #25-1-5.4. Cor. lies in cutting lines. Clear cut NW of corner.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 9/17/2024 - C.S. File 67/59-3

Found - DCS0 2½" brass cap (properly mkd) on 1" I.D. iron pipe, proj 12"
6" rotted Fir stub N.83°W., 19.8 ft.
16" D.Fir N.29°E., 53.0 ft., fully healed double blaze, 3½" mag nail, right side center.
Rotted, broken 15"x4" Fir stub S.81°W., 22.3 ft, blaze rotted away.
18" D.Fir S.22°W., 42.0 ft. fully healed double blaze, 3½" mag nail, right side center.
16" D.Fir N.83°E., 57.2 ft. fully healed double blaze, 3½" mag nail, right side center.
Spike and tag in 18" rotted and broken Fir stump N.86°W., 19.1 ft.
Note - Area burnt 9/2020
Compass decl. 14¼°E.
Corner lies on steep NW'ly slope approx 200' easterly of the end of BLM road #25-15.4 corner lies in cutting line, older reprod NW of corner.
Oregon Coordinate Reference System
Cottage Grove - Canyonville Zone
N 225989.007 E 295075.202