

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 20 & 21

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Carl S. Nicklin, Dep. Surveyor under contract # 664, dated May 23, 1896 - (DCSO recs Vol. 7 Page(s) 2830)  
-----  
Set a hemlock post, 4 ft. long, 4" sq., 24" in the ground, for 1/4 sec. cor. marked 1/4 S on W face, from which  
    A fir, 12" dia., bears N.7°E., 44 lks., mkd: 1/4 S BT.  
    A fir, 36" dia., bears N.14 1/2°W., 35 lks., mkd: 1/4 S BT.  
This cor. is on a hillside sloping N about 100 ft. below ridge.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Vernon Tracy - Clete Putnam - Oct. 1961 - C.S. File 52/42-3  
-----  
Found - Dead Fir snag, now 15" N.7°E., 29.0 ft., not completely grown over, good scribing "1/4 S BT", plainly visible.  
    Fir tree, approx. 38" N.14 1/2°W., 23.1 ft. (to center of tree) Very good axe scar, did not open.  
Set - Brass cap mkd: COUNTY SURVEYORS OFFICE, 1961 T24S R1W 1/4 S20|S21  
    10" Hemlock N.8°E., 13.0 ft., mkd: 1/4 S21 CS BT.  
    7" Yew N.82°W., 3.7 ft., mkd: 1/4 S20 CS BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Vincent Perron - May 28, 1970 - C.S. File 54/27-195  
-----  
Found - 1961 county brass cap in place. 1961  
    Orig. now 38" Fir N.14 1/2°W., 29.0 ft., alive, shows scar.  
    Other orig. BT gone.  
    10" Hemlock, alive, N.8°E., 13.0 ft., blaze healing.  
    The Yew BT to NW now broken off just above "BT" scribe.  
New BT - 15" Hemlock S.82°W., 43.3 ft., mkd: "1/4 S20 CS BT"  
Note - This corner lies approx. 500 ft. E of Scaredman access rd & at SW corner of cutoff unit in Sec 21

Fd. & used on BLM Dependent resurvey by James E. Jelley & Wayne L. Rogers, Cadastral Surveyors under Group #1051 surveyed April 1981/Sept. 1982 - (DCSO records Vol. 45 Page(s) 17335)