

TOWNSHIP 24 RANGE 01 POINT IDENTIFIER # 300400

PRIMARY CORNER DESCRIPTION Cor. Secs 16, 17, 20, & 21

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Carl S. Nicklin, Dep. Surveyor under contract # 664, dated May 23, 1896 - (DCSO recs Vol. 7 Page(s) 2831-2)

Set a yew post, 4 ft. long, 4" sq. 24" in the ground, for cor. to secs. 16, 21, 20, & 17, marked T24S S16 on NE, R1W S21 on SE, S20 on SW, S17 on NW faces, with 4 notches on E & 3 notches on S edges; from which

A pine, 8" dia., bears N.40°E., 79 lks., mkd: T24S R1W S16 BT.

A hemlock, 14" dia., bears S.27°E., 54 lks., mkd: T24S R1W S21 BT.

A hemlock, 18" dia., bears S.80°W., 95 lks., mkd: T24S R1W S20 BT.

A fir, 24" dia. bears N.43°W. 17 lks. mkd: T24S R1W S17 BT
This corner is on a hillside, sloping S about 25 ft. above creek.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Vernon Tracy - Clete Putnam - Oct. 1961 - C.S. File 52/42-6

Found - Pine tree, now 21" N.40°E., 50.3 ft., (instead of 52.1 ft) shows good scar, did not open.

Fir tree, now 30" N.43°W., 11.2 ft., shows good scar did not open. (These 2 on steep slope.)

Hemlock tree, now 26", S.80°W., 62.7 ft. Scar opened previously & scribing visible, "24 1W S20". These 3 trees in good condition.

Hemlock tree, now 28" S.27°E., 33.3 ft. (instead of 35.6 ft.) opened previously & scribing visible "4S S21" top of tree dead, will probably not last many more years. Top of tree dead, will probably not last many more years.

Set - Brass cap mkd: COUNTY SURVEYORS T24S R1W S 17|S 16
OFFICE 1961 S 20|S 21

New BT- 13" Hemlock S.7½°E. 31.9 ft. mkd: T24S R1W S21 CS BT