TOWNSHIP 24 RANGE 01 POINT IDENTIFIER # 300440

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 16 & 17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Carl S. Nicklin, Dep. Surveyor under contract # 664, dated May 23, 1896 - (DCSO recs Vol. 7 Page(s) 2833)

Set a fir post, 4 ft. long, 4" sq., 24" in the ground, for ¼ sec. cor. marked ¼ S on W face, from which
A fir, 18" dia., bears S.17½°E., 22 lks., mkd: ¼ S BT.
A fir, 10" dia., bears S.82°W., 12 lks., mkd: ¼ S BT.
This cor. is on a hillside, sloping W about 50 ft. below ridge.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy Co. Surveyor - Clete Putnam - June 4, 1962 - C.S. File 52/42-16

Found - 18" Fir, S.17½°E., 14.5 ft., scribing visible "¼ SBT" blaze had never grown over.
10" Fir snag N.82°W. 7.9 ft. scribing visible "¼SBT" (notes say S.82°W.) blaze had never grown over.
Set - Brass cap at cor. mkd: COUNTY SURVEYORS OFFICE 1962
T24S R1W ¼ S17|S16
New BTs- 10" Hemlock N.73½°W., 7.6 ft., mkd: ¼ S17 CS BT
17" D.Fir S.67°E., 26.1 ft., mkd: ¼ S16 CS BT

Fd. Ok by T. Shrum 11/1980 - M84-55