

TOWNSHIP 24 RANGE 01 POINT IDENTIFIER # 400200

PRIMARY CORNER DESCRIPTION Cor Secs 27, 28, 33, & 34

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Carl S. Nicklin, Dep. Surveyor under contract # 664, dated May 23, 1896 - (DCS0 recs Vol. 7 Page(s) 2812)

Set a pine post, 4 ft. long, 4" sq. 24" in the ground, for cor. to secs. 27, 34, 33, & 28, marked T24S S27 on NE, R1W S34 on SE, S33 on SW, S28 on NW faces, with 3 notches on E & 1 notch on S edges; from which

A fir, 8" dia. bears N.66°E., 34 lks. mkd: T24S R1W S27 BT
A chincapin, 6" dia., bears S.34°E., 8 lks., mkd: T24S R1W S34 BT.

A fir, 10" dia. bears S.41°W. 27 lks. mkd: T24S R1W S33 BT
A chincapin, 8" dia., bears N.47°W., 24 lks., mkd: T24S R1W S28 BT.

This cor. is on top of a spur sloping S about 200 ft. above ¼ sec. cor.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy Co. Surveyor - Vernon Tracy - Clete Putnam - Oct. 1961 - C.S. File 52/42-7

Found - Mound of rocks.
Fir tree now 24" N.68°E. 22.4' (instead of N.66°E.) 22.4 ft., shows good scars. Tree in good cond.
Chinq. now 8", S.29°E., 5.3 ft. (instead of S.34°E.) 5.3 ft face badly rotted but scribing "BT" vis.
Pine tree, instead of Fir, now 24" S.42°W., (instead of S.41°W.) 17.8 ft., shows scars. Blaze 7
rescribe this tree "T24S R1W S33 CS BT"
NW BT not found.

Set - Iron pipe with Brass cap mkd: COUNTY SURVEYORS OFFICE 1961 T24S R1W S 28 | S 27
S 33 | S 34
17" D.Fir N.32½°W., 24.3 ft. mkd: T24S R1W S28 CS BT
13" D.Fir S.47¼°E., 26.3 ft. mkd: T24S R1W S34 CS BT

Fd. Ok by VRT, DCS0 - May 1970 C.S. File 54/27-197

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 10/29/1996 - C.S. File 65/9-23

Found - 2½" dia. DCS0 brass cap on a 1½" O.D. iron pipe. protrudes 11" above ground. Is surrounded by a 1 ft. mound of stone. 1961
6" now 7" dia. 5 ft. high rotted Chinquapin snag, with a rotted blaze, no scribing visible, bears S.29°E., 5.3 ft. (agrees with 1961 rec.) O.B.T.

continued next page

TOWNSHIP 24 RANGE 01 POINT IDENTIFIER # 400200

PRIMARY CORNER DESCRIPTION Cor Secs 27, 28, 33, & 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

10" now 22" dia. 70 ft. high dead Pine snag, with an unhealed double blaze, scribing visible "T24S R1W S33 CS BT" bears S.42°W., 17.8 ft (agrees with 1961rec.) O.B.T.
No other original BT's found.
13" now 12" dia. 4 ft. high rotted D.Fir stump with scribing visible on a partially healed double blaze "R1W" bears S.47½°E., 26.3 ft. (agrees with rec.) 1961
SW BT from 1961 now gone.
New BTs- 12" dia. D.Fir, double blazed and scribed "T24S R1W S28 CS BT" bears N.84½°W., 21.7 ft.
5" dia. Hemlock, double blazed and scribed "T24S R1W S33 CS BT" bears S.33°W., 6.4 ft.
6" dia. D.Fir, double blazed and scribed "T24S R1W S27 CS BT" bears N.16°E. 19.6 ft.
3" dia. pistol butt Hemlock, double blazed and scribed "X BT", bearing and distance taken at upper blaze on straight trunk, bears S.73°E., 14.3 ft.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 7/31/2023 - C.S. File 67/56-53

Found - DCS0 brass cap (properly mkd) 2½" up 11" in mound of stone.
22"x70' pine snag, S.42°W., 17.8 ft. with unhealed double blaze.
13"x2' broken rotted fir stump, N.47½°E., 26.1 ft. blaze gone.
15" D.Fir M.84½°W., 21.7 ft. fully healed double blaze.
10" Hemlock S.33°W., 6.4 ft. fully healed double blaze.
11" D.Fir N.16°E., 19.6 ft. fully healed double blaze.
Down 9" Hemlock S.73°E., 14.3 ft. fully healed high-low blaze, bearing & distance ok to root hole.
New - 9" Hemlock S.45°E., 15.7 ft. scribed "T24S R1W S34" "CSBT" on double blaze 4" steel nail, right side center.
Compass decl. 14½°E.
Note - Area burnt 9/2020
Corner on flat ground in older reprod forest.
Oregon Coordinate Reference System
Cottage Grove - Canyonville Zone
N 225950.569 E 305529.089

