

TOWNSHIP 24 RANGE 01 POINT IDENTIFIER # 400340

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 21 & 22

|             |                   |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

GLO survey by Carl S. Nicklin, Dep. Surveyor under contract # 664, dated May 23, 1896 - (DCSO recs Vol. 7 Page(s) 2817)  
-----  
Set a basalt stone 10x8x8" 7" in the ground for ¼ sec. cor. marked ¼ on W face, from which  
    A hemlock, 60" dia., bears N.32°E., 21 lks., mkd: ¼ S BT.  
    A hemlock, 6" dia., bears N.5°W., 35 lks., mkd: ¼ S BT.  
This corner is on a hillside, sloping NE about 75 ft. below last spur.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy- V. Tracy - M. Stone - Sept. 1962 - C.S. File 52/42-26  
-----  
Found - Rock mkd: "¼" lying alongside corner location.  
        9" Hemlock N.5°W., 23.1 ft. cut open & fd. good scribing "BT". Blaze & rescribe this tree "¼ S21 CS BT"  
        18" Hemlock N.32°E., 13.9 ft., shows good scar. Did not open.  
Set - Brass cap at cor. mkd: COUNTY SURVEYORS OFFICE 1962  
            T24S R1W ¼ S21|S22  
        Pile mound of rocks around cap. Place corner rock alongside.  
New BT - 8" R.Cedar N.78°W., 10.3 ft., mkd: ¼ S22 CS BT.  
        Corner lies under overhang of Rock Bluff 25 ft. high