

TOWNSHIP 24 RANGE 01 POINT IDENTIFIER # 400500

PRIMARY CORNER DESCRIPTION Cor Secs 9, 10, 15, & 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Carl S. Nicklin, Dep. Surveyor under contract # 664, dated May 23, 1896 - (DCSO recs Vol. 7 Page(s) 2820)

-----  
Set a basalt stone, 12x10x6", 8" in the ground for the cor. of secs. 10, 15, 16, & 9 marked with 4 notches on S & 3 notches on E edges, from which

A fir, 16" dia., bears N.39°E., 54 lks., mkd: T24S R1W S10 BT.

A cedar, 42" dia., bears S.41½°E., 10 lks., mkd: T24S R1W S15 BT.

A W.Fir, 16" dia., bears S.38°W., 65 lks., mkd: T24S R1W S16 BT.

A cedar, 10" dia., bears N.32°W., 41 lks., mkd: T24S R1W S9 BT.

This cor. is on the left bank of creek.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Vernon Tracy - Clete Putnam - Oct. 1961 - C.S. File 52/42-13

-----  
Found - Rock set in ground mkd. as called for in Gov. notes. Cedar tree, now 40", S.40°E., 6.6 ft. scribing visible on rotting face. "4R1". Reblaze & scribe this tree.

W.Fir, now 30", S.38°W. 42.9 ft. shows 2 good scars. Tree in good condition. Did not rescribe.

Cedar, now 16" portions of scribing visible in nearly closed scar. Tree nearly dead, N.32°W., 27.1 ft.

Dead Fir snag, now 24" N.39°E., 35.6 ft. shows good scars.

Set - Brass cap mkd: COUNTY SURVEYORS T24S R1W S 9|S 10  
made rock mound. OFFICE 1961 S 16|S 15

New BTs- 20" Cedar north 19.8 ft., mkd: T24S R1W S10 CS BT.  
7" Yew N.35°W., 5.8 ft., mkd: T24S R1W S9 CS BT.

FD. Ok - T. Shrum, 11/1980 - M 84-55