

TOWNSHIP 24 RANGE 01 POINT IDENTIFIER # 500200

PRIMARY CORNER DESCRIPTION Cor. Secs. 26, 27, 34, & 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Carl S. Nicklin, Dep. Surveyor under contract # 664, dated May 23, 1896 - (DCSO recs Vol. 7 Page(s) 2799)

Set a chincapin post, 4 ft. long, 4" sq. 24" in the ground, for cor. to secs. 26, 35, 34, & 27, marked T24S S26 on NE, R1W S35 on SE, S34 on SW, S27 on NW faces, with 1 notch on S & 2 notches on E edges; from which
A fir, 36" dia. bears N.38°E. 38 lks. mkd: T24S R1W S26 BT
A fir, 48" dia. bears S.68°E. 48 lks. mkd: T24S R1W S35 BT
A cedar, 10" dia., bears S.62°W., 49 lks., mkd: T24S R1W S34 BT.
A fir, 42" dia. bears N.41°W. 58 lks. mkd: T24S R1W S27 BT
This cor. is on a steep hillside, sloping SW about 75 ft. above creek.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - V. Perron - May 1970 - C.S. File 54/27-213

Found - Orig. 36", now 38" Fir, alive N.38°E., 25.1 ft., shows good scar, we tag.
Orig. 48", now 54" Fir, alive, S.68°E., 31.7 ft., shows good scar, we tag.
Orig. 10", now 15" Cedar, alive, S.62°W., 32.3 ft., broken top, we open & find "S" scribe & reverse.
No trace of NW orig. BT
Set - Brass cap at cor. mkd: County Surveyors T24S R1W
Office S 27 | S 26
1970 S 34 | S 35

New BTs- 8" Hemlock S.51°W., 35.5 ft. mkd: T24S R1W S34 CS BT
20" Hemlock N.89°W. 18.0 ft. mkd: T24S R1W S27 CS BT
This corner lies on very steep, westerly slope, approx. 75 ft., E of creek.