

TOWNSHIP 24 RANGE 01 POINT IDENTIFIER # 500640

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 2 & 3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Carl S. Nicklin, Dep. Surveyor under contract # 664, dated May 23, 1896 - (DCSO recs Vol. 7 Page(s) 2811)

-----

Set a basalt stone 14x12x8" 10" in the ground for ¼ sec. cor. marked ¼ on W face, from which

A hemlock, 12" dia., bears S.67°E., 43 lks., mkd: ¼ S BT.

A cedar, 60" dia., bears N.88°W., 9 lks., mkd: ¼ S BT.

This cor. is on right bank of creek, about 125 ft. below top of spur, last noted.

Douglas Co. Surveyors Office - V.R. Tracey - April 1970 - C.S. File 54/27-203

-----

Not found.

We find no trace of OBTs - probably destroyed by 1964 flood.