

TOWNSHIP 24 RANGE 01 POINT IDENTIFIER # 540300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 23 & 26, WC

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Carl S. Nicklin, Dep. Surveyor under contract # 664, dated May 23, 1896 - (DCSO recs Vol. 7 Page(s) 2803)

Set a basalt stone, 12x8x8", 9" in the ground for 1/4 sec. cor. marked 1/4 on N face, from which

A fir, 16" dia., bears N.35°W., 37 lks., mkd: 1/4 S BT.

A fir, 12" dia., bears S.55°E., 3 lks., mkd: 1/4 S BT.

This cor. is on a point of land, bet. fork of creeks.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy Co. Surveyor - Vernon Tracy - Clete Putnam - Oct. 1961 - C.S. File 52/42-12

Found - 22" Fir tree N.35°W., 24.4 ft., cut open & fd. good scribing "S"

17" Fir tree S.55°E., 2.0 ft., uprooted & down. Cut open & fd good scribing "4"

Note - Corner position & SE tree are right in edge of stream at forks of Canton Creek. Impractical to set brass cap in this position.

Set - Wit. cor. to 1/4 cor. 70 ft. South of corner position. Set iron pipe with brass cap mkd:

County Surveyors Office 1961

T24S R1W WC 1/4 S23/S26 made rock mound

New BTs- 16" Hemlock S.49°E., 21.5 ft. mkd: S26 WC CS BT

The orig. NW BT bears N.9°W., 91.6 ft. Did not rescribe.