TOWNSHIP 24 RANGE 01 POINT IDENTIFIER # 540400

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 14 & 23

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Carl S. Nicklin, Dep. Surveyor under contract # 664, dated May 23, 1896 - (DCSO recs Vol. 7 Page(s) 2805)

Set a chincapin post, 3½ ft. long, 3" sq., 24" in the ground, for ¼ sec. cor. marked ¼ S on N face, from which
A cedar, 16" dia., bears N.5°W., 55 lks., mkd: ¼ S BT.
A chincapin, 6" dia., bears S.55°W., 15 lks., mkd: ¼ S BT.
This cor. is on a hillside, sloping W about 20 ft. below top of spur.

Douglas Co. Surveyors Office - Vernon R. Tracy & Crew - Oct. 26, 1966 - C.S. File 52/42-48

Found - Orig. 16" now 32" Cedar, N.5°W., 36.3 ft. Open & find "4 S" scribe & reverse.
No trace of other orig. BT T24S R1W
Set - Brass cap at cor. mkd: County Surveyors Office 1966 ¼ S 14 / S 23
New BTs- 8" Chinq. S.88°W., 18.3 ft. mkd: "¼ S23 CS BT"
8" D.Fir N.24°E., 6.3 ft. mkd: "¼ S14 CS BT"
Note - This corner lies very near the top of spur, ridge, course SW.

Fd. & used on BLM dependent resurvey by Glenn S. Baughman, reg. land surveyor #536, under contract #52500-CT5-1116, group #853, surveyed July 1975 - (DCSO records Vol. 38 page 15636)