

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 11 & 14

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Carl S. Nicklin, Dep. Surveyor under contract # 664, dated May 23, 1896 - (DCSO recs Vol. 7 Page(s) 2807-8)

-----

Set a cedar post, 3½ ft. long, 3" sq., for ¼ sec. cor. marked ¼ S on N face, from which

A fir, 12" dia., bears N.40°E., 6 lks., mkd: ¼ S BT.

A fir, 24" dia., bears S.42°W., 46 lks., mkd: ¼ S BT.

This cor. is on a steep hillside, sloping NW about 50 ft. below top of spur last noted.

Thomas W. Coiner, R.S. 413 - For: Bohemia Lumber Co., Inc. - Aug. 24, 1961 - Aug. 24, 1961 - C.S. File 51/209

-----

Determined from the orig. BTs & the hole where the orig. post was set. Post down but intact.

At the corner point: Set iron pipe in old post hole, 30x2x12" in the ground with alum. bronze cap mkd: ¼ S11/S14 from which:

A D.Fir 20" bears N.40°E., 4 ft., blaze healed.

A D.Fir 36" bears S.40°W., 31 ft., blaze healed.

BLM dependent resurvey by Glenn S. Baughman, reg. land surveyor #536, under contract #52500-CT5-1116, group #853, surveyed July 1975 - (DCSO records Vol. 38 page 15637)

-----

The ¼ sec. cor. of secs. 11 & 14, perpetuated & recorded by person(s) unknown, monumented with an iron pipe 1½" dia., loosely set, protruding 18" above ground, with alum. cap mkd: ¼ S11 S 14, from which the remains of the orig. BTs:

A fir, 20" dia., bears N.40°E., 6 lks., with healed blaze.

A fir snag, 34" dia., bears S.40°W., 46 lks. with scribe marks ¼ visible on opened blaze. (Rec. S.42°W.)

At the corner point

Set an iron post, 28" long, 2½" dia., 25" in the ground, with brass cap marked:

T24S R1W

¼       S  11

          S 14

          1975

from which a new BT

A hemlock, 6" dia., bears S.7°W., 25 lks., mkd: ¼ S14 BT.

Reset iron pipe alongside iron post.