

TOWNSHIP 24 RANGE 01 POINT IDENTIFIER # 600140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 35 & 36

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Carl S. Nicklin, Dep. Surveyor under contract # 664, dated May 23, 1896 - (DCSO recs Vol. 7 Page(s) 2784)

Set a basalt stone 8x8x8" 6" in the ground for ¼ sec. cor. marked ¼ on W face, from which
 A fir, 18" dia., bears N.75°E., 37 lks., mkd: ¼ S BT.
 A fir, 36" dia., bears N.73°W., 21 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - Oct 1967 - C.S. File 52/42-58

Found - Orig. 18", now 34" Fir sawed stump, N.75°E., 24.4 ft., open & find "BT" scribe & reverse.
 No trace other orig. BT now corner stone.
Set - Brass cap at cor. mkd: COUNTY SURVEYORS T24S R1W OFFICE 1967 ¼ S 35|S 36
New BTs- 14" Cedar N.75°W., 21.5 ft., mkd: ¼ S35 CS BT
 12" Hemlock stump S.31°E., 9.5 ft., mkd: ¼ S36 CS BT
 No live trees east of line due to clear cut logging.
Note - This corner lies on very steep, northerly slope, approx. 270 ft. south of Canton Creek.