

PRIMARY CORNER DESCRIPTION Cor Secs 13, 14, 23, & 24

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Carl S. Nicklin, Dep. Surveyor under contract # 664, dated May 23, 1896 - (DCSO recs Vol. 7 Page(s) 2790)

-----

Set a basalt stone, 12x10x8", 9" in the ground, for cor. of secs. 13, 24, 23, & 14, marked with 3 notches on S & 1 notch on E edges. From which

- A fir, 8" dia. bears N.26°E., 26 lks. mkd: T24S R1W S13 BT
- A fir, 8" dia. bears S.48°E., 21 lks. mkd: T24S R1W S24 BT
- A fir, 30" dia. bears S.53°W. 27 lks. mkd: T24S R1W S23 BT
- A fir, 6" dia. bears N.48°W., 33 lks. mkd: T24S R1W S14 BT

This cor. is on a steep, rocky hillside, sloping West.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Joe Brady - Jack Heritage - Aug 1966 - C.S. File 52/42-46

-----

Found - 12"x10"x8" basalt stone w/3 notches on S side & 1 notch on E.

- Orig. 8" now 16" Fir N.26°E., 17.2 ft. Alive, shows very good scar.
- Orig. 8" now 17" Fir, S.48°E., 13.9 ft. Alive, shows good scar. Do not open.
- Orig. 30" now 33" Fir, S.53°W., 17.8 ft., now snag, shows scribe on unhealed blaze.
- Orig. 6" now 9" Fir, N.48°W., 21.8 ft. Alive, shows good scar. Do not open.

Set - Brass cap at cor. mkd: County Surveyors Office 1966

T24S	R1W
<u>S 14</u>	<u>S 13</u>
S 23	S 24

B.C. in mound of stone 3' wide at base & 2' high & orig. Stone alongside.

New BT - 8" D.Fir S.50°W., 11.0 ft. mkd: T24S R1W S23 CS BT.

Note - This corner lies approx. 300 ft. W of top of ridge, course N & S.

Douglas Co. Surveyors Office - M. Lenora Ladig - Pete Earle - Debby Stewart - April 13, 1976 - C.S. File 59/8-16

-----

Found - 1966 County Surveyors Office brass cap laying on ground. 1966

- Orig. 8" now 16" Fir, N.26°E., 17.2 ft., alive & well healed. Lower part of tree cut into.
- Orig. 8" now 17" Fir S.48°E., 13.9 ft. alive & well healed.
- Orig. 30" now 33" Fir snag S.53°W., 17.8 ft. Visible "T24 R1 S T" on unhealed blaze.
- 8" now 10" D.Fir S.50°W., 11.0 ft. Visible "4 1 2 C B" in good blaze.

Intersected dist. & bearings of the 5 BTs. cont. next pg.

PRIMARY CORNER DESCRIPTION Cor. Secs. 13, 14, 23, & 24

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Set - At true corner point, the 1966 DCSO brass cap in mound of stone 4 ft. wide at base & 14" high, stamped 1976 above 1966 at bottom.  
New BT - 13" D.Fir bears N.29°W., 32.4 ft., scribed "T24S R1W S14 CS BT" in double blaze.  
Note - Corner lies approx. 300 ft. west of top of N-W ridge. Cor. also lies approx. 90 ft. west of Rd. #24-1-11  
Compass dec. 20° East.

Douglas Co. Surveyors Office - Larry E. Monrean, Deputy - Randall W. Smith - Oct. 13, 1986 - C.S. File 59/30  
-----  
Found monument & accessories as described in last renewal. From fd. DCSO brass disk & iron pipe set:  
Bearing object 1, a 5/8" iron rod with alum. cap, bears N.05°E., 524.52 ft.  
Bearing object 3, a 5/8" iron rod with alum. cap, bears N.33°E., 577.83 ft.  
Bearing object 4, a 5/8" iron rod with alum. cap, bears N.49°E., 418.82 ft.  
Corner approx. 80 ft. West of F.S. Rd. #24-1-1.0. Area is to be logged in near future, section corner will probably be destroyed.  
Sketch & horizontal directions are filed in C.S. 59/30

Douglas Co. Surveyors Office - Randall W. Smith - Stephen J. Flause - 11/17/1986 - C.S. File 59/30  
-----  
Area of section corner to be logged in near future. To protect against corner loss we pull up & replace DCSO brass cap/iron pipe per 1976 ren. with a DCSO drill cap marked as noted: DOUGLAS COUNTY SURVEYORS OFFICE T24S S14 S13 S23 S24 R1W 1986.  
Drill cap set in bedrock. Several PK nails driven in rock surrounding brass cap & three boat spikes set randomly over brass cap for future magnetic locating. Drill cap is set 18" under ground surface.  
PK nails with flagging set in base of BTs, PK nails are oriented approx. at corner.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - Aug. 28, 1989 - C.S. File 64/3-2  
-----  
Found - 1986 DCSO 3" dia. drill cap set in rock, 18" below ground.  
  
continued next page

PRIMARY CORNER DESCRIPTION Cor Secs 13, 14, 23, & 24

Alias	Description
Alias	Description
Alias	Description
Alias	Description

8" now 14" dia., 5 ft. high D.Fir stump, with an opened blaze, no scribing seen, bears N.26°E., 17.2 ft. OBT

8" now 18" dia., 6 ft. high D.Fir stump with fully healed blaze bears S.48°E., 13.9 ft. OBT

6" now 10" dia., 6 ft. high D.Fir stump with partially healed blaze, no scribing seen bears S.42°W., 11.0 ft. (Rec. S.50°W., 11.0 ft.) OBT

13" now 16" dia., 4½ ft. high D.Fir stump with fully healed double blaze bears N.31°W., 32.4 ft. (Rec. N.29°W., 32.4 ft.) 1976

5/8" I.R. with DCSO alum. cap stamped "3" protrudes 10" above ground bears N.33°E., 557.83 ft. 1986

5/8" I.R. with DCSO alum. cap stamped "4" slash pile interferes with a direct measurement. (Rec. N.49°E., 418.82 ft.) 1986

Orig. 30" now remains of roots at record bearing & dist. (Rec. S.53°W., 17.8 ft.)

Set - 5/8" iron rod with alum. cap "1" from 1986 not fd.  
 2 3/8" dia., DCSO brass cap on a 1 3/8" O.D. x 32" long iron pipe is set at a referenced position plumb over 1986 DCSO drill cap. BC/IP protrudes 2" above a 2½ ft., dia., mound of stone & mkd:  
 DOUGLAS COUNTY SURVEYORS T24S S 14|S 13 R  
 OFFICE S 23|S 24 1  
 1989 W

New - A Boat spike set through a BT tag into a 16" dia., 4 ft. high D.Fir stump. Spike is stamped "BO B" bears N.75½°W., 25.8 ft.  
 A Boat spike set through a BT tag into a 15" dia., 2½ ft. high D.Fir stump. Spike is stamped "BO A" bears S.17½°W., 27.5 ft.

Corner lies on steep west slope in a new clear cut approx. 100 ft. west of road.