

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 1 & 2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Carl S. Nicklin, Dep. Surveyor under contract # 664, dated May 23, 1896 - (DCSO recs Vol. 7 Page(s) 2796)

 Set a hemlock post, 4 ft. long, 4" sq., for 1/4 sec. cor. 24" in the ground, marked 1/4 S on N face, from which
 A fir, 34" dia., bears N.64°W., 19 lks., mkd: 1/4 S BT.
 A fir, 26" dia., bears S.73°E., 23 lks., mkd: 1/4 S BT.
 This cor. is on a steep hillside, sloping E, about 25 ft., above creek.

Douglas Co. Surveyors Office - Milo Godfrey - & Crew - Nov. 5, 1962 (added 10/31/2017) - C.S. File 54/27-200

 Reported as not found
 Found 3 scribed trees. Scribing approx. right age for survey of this area. One scribed tree faces about right for SE BT but no tree would have fit NW BT.
 Also, BTs were not marked properly for 1/4 cor. - scribing I saw on 2 trees was "R 27 M BT"
 Also, cor. set from these BTs would fall squarely on top of ridge, instead of 1.50 chs. north of ridge top, as called for in line notes.
 No N & S blazed line was fd. - Nicklin's section lines are usually well blazed.
 I do not know what these scribed trees are witness to, but I do not believe it is the sec. cor. Signed Milo E. Godfrey

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - V. Perron - April 1970 - C.S. File 54/27-200

 Found - Orig. 8", now 20" Fir S.72°E., 33.7 ft., open & find "S" scribe.
 Orig. 18" now 30" Fir, alive, N.70°E., 42.9 ft., shows good scars, we tag.
 Set - Brass cap at cor. mkd: County Surveyors T24S R1W Office 1970 1/4 S 2|S 1
 New BTs- 10" D.Fir S.59°E., 16.2 ft., mkd: "1/4 S1 CS BT"
 22" D.Fir S.66°W., 8.9 ft., mkd: "1/4 S2 CS BT"
 This corner lies on very steep, north slope 95 ft., N of ridge top. We put line tag on Leach Cap Jeep Trail. At a point about 500' W & on ridge top, are trees with scribe marks "R27M" & BT.

FD. Ok by V.R.T., DCSO - 7/25/1973 - C.S. File 56/34-6 Pg2

continued next page

TOWNSHIP 24 RANGE 01 POINT IDENTIFIER # 600640

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 1 & 2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Dependent resurvey by Joseph M. Mannix, Cadastral Surveyor under Group No. 2763, surveyed April/July 2015 - (DCSO records Vol. 58 Page(s) 23396)

The ¼ sec. cor. of secs. 1 and 2, perpetuated by the Douglas Co. Surveyor's Office, in 1970, monumented with an iron post, 1¼" dia., firmly set, projecting 2" above ground, with a brass cap (properly) mkd.

from which the original bearing trees

A fir, 24" dia., bears S.72°E., 33.7 ft., with illegible scribe marks visible on an open blaze.

A fir, 32" dia., bears N.70°W., 42.9 ft., with a healed blaze.

and the BTs mkd. by the Douglas County Surveyor's Office

A fir, 11" dia., bears S.59½°E., 16.2 ft., with a healed blaze.

A fir, 29" dia., bears S.66°W., 8.9 ft., with a healed blaze.