

PRIMARY CORNER DESCRIPTION 1/4 Cor. for sec. 1; & 36, T23-1

Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCSO records Vol. 5 Page(s) 2139)

-----  
 Set a post 4 ft. long, 4" sq., 24" in the ground mkd. ¼ S on N. face, for ¼ sec. cor., from which  
     A Hemlock 12" dia., bears N.16 3/4°W., 42 lks. dist. mkd. ¼ S BT.  
     A Hemlock 30" dia., bears S.76½°W., 44 lks. dist. mkd. ¼ S BT.

Douglas Co. Surveyors Office - Gary L. Langlitz; A. Vic Cangie; M.L. Tompkins; - Oct. 28, 1976 - C.S. File 59/24

-----  
 Found - An orig. 12" now 24" Hemlock, down and rotten with illegible scribe marks visible on a previously opened blaze.  
         An orig. 30" now 36" Hemlock, alive and in good condition with illegible scribing visible on previously opened blaze.  
         The original corner post is gone.  
 At the corner point as determined by the found orig. BTs as follows:  
         A down 24" hemlock, bears N.16 3/4°W., 27.7 ft.  
         36" hemlock bears S.76½°W., 29.0 ft.

We Set a 1" x 30" Iron pipe 26" in the ground on a steep East slope approx. 30 ft. West of a small ravine, with brass cap attached, marked: Douglas Co. Surveyor

	T 23 S	
1	<u>S 36</u>	R
/	S 1	1
4	T 24 S	W
	1976	

from which we mark the following:  
     A 6" Hemlock bears N.40½°E., 9.9 ft. scribed "¼ S36 CS BT" on a single blaze.