

TOWNSHIP 24 RANGE 01 POINT IDENTIFIER # 700200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 25 & 36; 30 & 31, T24-1E

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Carl S. Nicklin, Deputy Surveyor, under joint contract #664 dated May 23, 1896 (DCSO recs Vol. 7 Page 2774)

Set a Hemlock post 4½ ft. long, 4" sq., 24" in the ground, for cor. of secs. 25, 30, 31 and 36, marked T24S S30 on NE.; R1E S31 on SE.; S36 on SW.; and R1W S25 on NW. faces; with 5 notches on N. and 1 notch on S. edges, from which

A Hemlock 6" dia., bears N.56°E., 25 lks. dist. mkd. T24S R1E S30 BT.

A Fir 6" dia., bears S.34°E., 22 lks. dist. mkd. T24S R1E S31 BT.

A Cedar 12" dia., bears S.77°W., 36 lks. dist. mkd. T24S R1W S36 BT.

A Cedar 24" dia., bears N.40°W., 65 lks. dist. mkd. T24S R1W S25 BT.

Cor. is on a steep hillside, sloping N.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew April 12, 1970 - C.S. File 54/27-207

Found - Orig. 6" now 14" Fir, alive, S.34°E., 14.5 ft., shows good scar. We rescribe "T24S R1E S31 CS BT".

Orig. 12" Cedar now 20 Hemlock stump, S.77°W., 23.8 ft., shows good scar.

Orig. 24" now 30" Cedar, alive, N.40°W., 42.9 ft., scribe marks visible on nearly healed blaze. Rescribe "T24S R1W S25 CS BT".

Orig. BT to NE. down, shows scar.

Set Brass cap at cor. mkd: County Surveyors Office

R	T 24 S	R
---	--------	---

1	S 25 S 30	1
---	-------------	---

W	S 36 S 31	E
---	-------------	---

1970

New BTs- 15" Hemlock N.82°E., 39.9 ft. mkd. "T24S R1E S30 CS BT."

9" Cedar S.8°W., 23.3 ft. mkd. "T24S R1W S36 CS BT".

Corner lies near bottom of N. slope, approx. 40 ft. from flat bench to N.

Steven Anderson - 3/20/1980 - C.S. File 54/27

CORNER REPORT ONLY

Found brass cap in good condition. Found BTs as follows:

18" Hemlock, N.82°E., 39.9 ft., closed scribe, good condition. 1970 BT.

Cedar, N.40°W., 42.9 ft., scribe semi closed, good condition. Orig. BT. (Cont. Next Page)

TOWNSHIP 24 RANGE 01 POINT IDENTIFIER # 700200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 25 & 36; 30 & 31, T24-1E

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

11" Cedar S.82°E., 23.3 ft. (Rec. S.8°W., 23.3 ft.), open scribe, good condition. 1970 BT.
29" Hemlock stump, S.77°W., 32.8 ft. (Rec. S.77°W., 23.8 ft.), closed scribe, good condition. Forest Service BT tag.

Dan Saily, Lone Rock Timber - Crew: Brett Ragon, Alfredo Martinez & Trevor Clemo - 6/2025 - C.S. File 65/116-5

Found - 1970 DCS0 cap as per record (5 of 25 is sidewise)
24" Hemlock bears N.82½°E., 39.2' 1980 rec N.82°E., 39.9' with partly healed faces BT visible and we re-tag
37" Cedar bears N.39°W., 43.4' 1980 record N.40°W., 42.9' with healed face and tag
32" D.Fir bears S.34°E., 12.7' 1970 rec. S.34°E., 14.5' with healed face and DCS0 tag. This BT was shot with compass for bearing (14¼°E declination) and total station to center side for distance
New - 13" D.Fir bears S.82 ¾°W., 54.0'. We scribe T24S R1W S36 BT and tag

5½' tall galvanized steel U-post 1' north
Note - Fd 1970 DCS0 brass and iron pipe as per C.S. File 54/27-207, 1.2' above ground level. Corner lies in mixed aged burned timber on a north facing slope. BTs were measured with a TOPCON ES62 to nails at center face for angles and side center for distances, except as noted. The basis of bearing was obtained by running a random closed loop traverse from the corner of sections 25, 36, 30, and 31 to the quarter corner of sections 25 and 36. We marked the line extending westerly from this section corner to the quarter corner of section 25 and 36. From this survey by blazing, painting, tagging and ribboning true line.
The 5 mkd on the BC is turned 90° from vertical as shown

