

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 29 & 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by John McQuinn, Deputy Surveyor, under Contract #466 dated April 1883 - (DCSO recs. Vol. 7 Page(s) 2887)

Set fir post, 3 ft. long, & 3" sq., 24" in the ground for the 1/4 sec. cor. marked 1/4 on N face, from which:

A fir, 36" dia., bears S.5°E., 35 lks., mkd: 1/4 S BT.

A hemlock, 18" dia., bears N.8°W., 48 lks., mkd: 1/4 S BT.

BLM dependent resurvey Levi E Tallett, Cadastral Engineer (1951) and C. Albert White, Cadastral Surveyor (1963), under Group # 294, surveyed May 1951 - Aug 1963 - (DCSO records Vol. 32 Page(s) 13303)

The 1/4 sec. cor. of secs. 29 & 32, determined at rec. dist. from the orig. BTs:

A fallen hemlock, 24" dia., bears N.11 1/2°W., 48 lks., blaze partially healed, scribe marks 1/4 visible. This tree has been down approx. 2 yrs; the blaze is covered with 66 yrs. of overgrowth. (Rec bearing N.8°W)

A fir snag, 40" dia., bears S.11°E., 35 lks., with scribe marks 1/4 S BT visible on old bark blaze. (Rec. bearing S.5°E.)

AT the corner point

Set an iron post, 36" long, 1" dia., 22" in the ground to solid rock, & in a mound of stone 4 ft. base to top, with brass cap marked:

1/4 S 29
 S 32
 1951

from which

A sawed fir stump, 56" dia., bears S.42°45'E., 37 lks., mkd: 1/4 S32 BT.

A fir, 40" dia., bears N.53 1/2°W., 93 lks., mkd: 1/4 S29 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - Aug 1969 - C.S. File 54/27-254

Found - 1951 Cad. brass cap, firmly set & in place.

Orig. 40" Fir (snag) S.11°E., 23.1 ft., bark scribe still visible.

56" Fir stump S.42°45'E., 24.4 ft., scribe visible.

Set - 6.0 ft. steel fence post alongside brass cap.

There being no trees close, we set:

3/4" I.R. North 20.0 ft.

3/4" I.R. West 5.0 ft., from 1/4 cor.

This corner lies on NE slope in old logged area.

continued next page

1

TOWNSHIP 24 RANGE 02 POINT IDENTIFIER # 240200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 29 & 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Ron Rice, NW Land Surveying - Jason Collver - Sept. 6, 2012 -
C.S. File 65/77-35

Found - 1" dia. Iron post with BLM brass cap dated 1951
Orig. 40" Fir (snag) S.11°E., 23.1 ft., bark scribe
still visible. (Found 30" Fir snag with no marks)
56" Fir stump S.42°45'E. 24.4 ft scribe visible (Fd)
¾" I.R. North 20.0 ft. (Fd)
¾" I.R. West 5.0 ft., from ¼ cor. (Fd)
New - 22" D.Fir bears N.42°E., 3.7 ft., scribed ¼ S29 BT
Note - Corner has steel post adjacent to it. All BTs have
orange painted bands and yellow tags.
Decl. 16° East

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff
Lorsung- 10/25/2022 - C.S. File 67/55-11

Found - 2½" brass cap on 1" iron pipe up 4".
Burned stump 30"x7' Fir S.4½°E. 22.5 ft (rec S.11°E.
23.1 ft) 3½" mag nail rt side center. (Orig)
Burnt 50"x5' fir stump S.36½°E., 23.7 ft. (rec.
S.42°45'E., 24.4 ft) face gone 3½" mag nail top
center. BLM
¾" I.R. S.87°W., 5.1 ft. (rec. west 5.0 ft)
Burnt-sawn 25"x8' D.Fir stump N.42°E., 3.7 ft. 3½"
mag nail right side center. Rice
1¼" I.D. iron pipe not of record north 2.15 ft.
(protrudes 2")
Steel post adjacent to BC
Note - Corner is S.30°E., 90'± from end of gravel spur rd.
Area burnt 9/2020
Compass decl. 14½°E.
Corner on moderate north slope just south from ridge
saddle.
Lat: 43°26'43.64"N Long: 122°57'35.55"N