

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 5; & 32, T23-2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 5 Page(s) 2175)

Set Hemlock post 3 ft. long, 3" sq., 24" in the ground, for 1/4 sec. corner, marked 1/4 S. on N. face, from which
A Maple 6" dia., bears N.35°W., 24 lks. dist. mkd. 1/4 S BT
A Maple 5" dia., bears S.20°E., 24 lks. dist. mkd. 1/4 S BT

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCSO records Vol. 5 Page(s) 2183)

(39.50 chs.)
Old 1/4 sec. cor., a post bears S. 4.50 chs. I destroyed this cor. also the marks on the old bearing trees.
(40.00 chs. West)
Set a post 3 ft. long, 3" sq., 24" in the ground for 1/4 sec. cor. marked 1/4 on N. face, from which
A Vine Maple 5" dia., bears N.47°E., 16 lks. dist. mkd. 1/4 S BT.
A Fir 30" dia., bears S.60°E., 27 lks. dist. mkd. 1/4 S BT.

Weyerhaeuser Co. - 1958-1963 - C.S. File 53/106-8

Found - 30" Fir S.60°E., 17.82 ft., now 33" Fir stump, chopped out. (Orig. BT)
No trace of 5" Vine Maple N.47°E., 10.56 ft.
Set 5/8" x 30" Monel pipe with a 2" x 19.6 ft. black iron pipe, set 17 ft. NE., 3 ft. in ground.
BTs - 42" Fir stump N.24°E., 28.8 ft. "W" nail & plate.
33" Fir stump S.60°E., 17.8 ft. "W" nail & plate.
(orig. BT)