

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 28 & 33

Alias	Description

GL0 Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619 dated June 5, 1893 - (DCSO records Vol. 7 Page(s) 2913-4)

Set a basalt stone 16x9x6" 11" in the ground for ¼ sec. cor. marked ¼ on W face, from which
A hemlock, 6" dia., bears S.74°W., 28 lks., mkd: ¼ S BT.
A fir, 36" dia., bears N.70°W., 58 lks., mkd: ¼ S BT.

BLM dependent resurvey Levi E Tallett, Cadastral Engineer (1951) and C. Albert White, Cadastral Surveyor (1963), under Group # 294, surveyed May 1951 - Aug 1963 - (DCSO records Vol. 32 Page(s) 13300)

The ¼ sec. cor. of secs. 28 & 33, monumented with a basalt stone, 15x8x6", firmly set, marked ¼ on N face, from which the orig. BTs:
A fir, 50" dia., bears N.64½°W., 58 lks., blaze healed (Rec. bearing N.70°W.)
A hemlock, 12" dia., bears S.68°45'W., 20 lks., blaze partially healed, partial scribe marks visible. (Rec. S.74°W., 28 lks.)

At the corner point
Set an iron post, 36" long, 1" dia., 12" in the ground to solid rock, and in a mound of stone, 4 ft., base to top, with brass cap mkd:
¼ $\frac{S\ 28}{S\ 33}$
1951

from which
A fir, 60" dia., bears S.0¼°W., 63 lks., mkd: ¼ S33 BT.
Bury the orig. corner stone alongside the iron post.

Dan Baker - For: Weyerhaeuser Co. - 12/2018 - C.S. 65/103-2

Found - 2½" GL0 brass cap "1951" on 1" iron post (up 2 ft)
Marked - 9" Fir, N.15°E., 16.1' to spike side/center-scribed "¼S28 BT"
9" Sweeping Fir, S.53°E., 11.8' to spike side/center-scribed "¼S33 BT"
7" Fir, S.13°W., 9.3' to spike side/center-scribed "¼S33 BT"
5" Fir, N.74°W., 7.2' to spike side/center-scribed "¼S28 BT)
5 FT metal post alongside corner

continued next page

TOWNSHIP 24 RANGE 02 POINT IDENTIFIER # 340200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 28 & 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and Jeff Lorsung - 1/21/2026 - C.S. File 67/62-02

Found - 2½" BLM Brass cap on iron pipe in rough stone mound. Leans S.S.E. 0.9 ft.

¼ $\frac{S\ 28}{S\ 33}$
1951

Sawn - rotted - burnt 34" x 4 ft. fir stump N.70°W. 37.4 ft. (Rec N.64°W. 58 lks.) Fully healed single blaze.

Sawn - burnt 10" x 4 ft. fir stump N.20°E. 15.6 ft. (Rec N.15°E. 16.1 ft.) partly healed single blaze. All scribing visible.

Burnt - broken 11" x 12 ft. sweeping fir snag S.53°E. 12.2 ft. (Rec 11.8 ft.) partly healed single blaze. All scribes visible.

Burnt - broken off 8" x 3 ft. fir stump S.13°W. 9.9 ft. (Rec 9.3 ft.) partly healed single blaze. All scribes visible.

Sawn - burnt 6" x 1 ft. fir stump N.77°W. 6.7 ft. (Rec. N.74°W. 7.2 ft.) partly healed low blaze. Scribe BT visible.

All bearing trees are found with 6" steel side spikes.

Original dist. were to top of leaning monument. We plumbed monument and all distance to plumb position. Const. large mound of stone monument. Now proj. 4" above top of mound. Reset metal post 1.5ft. East.

Note - Area burnt 9/2020

Compass decl. 14¼°E.
TRIMBLE GEO XT POSITION
43°44929861 N.
122°94090599 W.