

TOWNSHIP 24 RANGE 02 POINT IDENTIFIER # 340700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 4; & 33, T23-2

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 5 Page(s) 2174)

-----  
Set a Dogwood post 3 ft. long, 3" sq., 24" in the ground for 1/4 sec. corner, marked 1/4 S on N. face, from which  
A Fir 70" dia., bears N.10°W., 8 lks. dist. mkd. 1/4 S BT.  
A Fir 36" dia., bears S.10°W., 53 lks. dist. mkd. 1/4 S BT

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCSO records Vol. 5 Page(s) 2182)

-----  
(40.00 chs.)  
Set a basalt stone 12x10x6 ins., 8" in the ground for 1/4 sec. cor., marked 1/4 on N. face, from which  
A Fir 40" dia., bears N.50°E., 32 lks. dist. mkd. 1/4 S BT  
A Fir 40" dia., bears S.15°E., 27 lks. dist. mkd. 1/4 S BT  
(41.00 chs. West)  
Old 1/4 sec. cor., a post bears South 80 lks. dist., I destroyed this post, also the marks on old bearing trees.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew July 1969 - C.S. File 54/27-106

-----  
Found - 12x10x6" basalt stone mkd. "1/4" and unrecorded Monel pipe, bent over.  
Orig. 40" now 50" Fir, turned out & 20 ft. downhill, N.50°E., 21.1 ft., open and scribe visible.  
Orig. 40" now 48" Fir, alive, S.15°E., 17.8 ft., shows good scar.

Set Brass cap at cor. mkd: County Surveyors Office  
T23S R2W 1/4 S 33  
T24S S 4  
1969

New BT - 48" D.Fir N.68°W., 24.5 ft. mkd. "1/4 S33 CS BT".  
No smaller trees available.  
Reset corner stone and monel pipe alongside brass cap.  
Corner lies on very steep NW. slope.