

TOWNSHIP 24 RANGE 02 POINT IDENTIFIER # 360200

PRIMARY CORNER DESCRIPTION East 1/16 Secs 28 & 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

V.W. Hosford - Dec. 1953 - C.S. File 40/110

Set - 3" Hemlock post for corner.
 A Hemlock, 10", bears N.85°E., 5.0 ft., mkd: 1/16 S28 PS 253 BT.
 A Fir, 16", bears N.88½°W., 17.3 ft., mkd: 1/16 S28 PS 253 BT.

V.W. Hosford - Sept. 1957 - C.S. File 42/306

At the E 1/16 S28 & 33, the BTs marked in my survey of 1953 are in good condition. At the true point of the corner I drove a 1½" iron pipe 30" long 18" in the ground.

Douglas Co. Surveyor's Office - Crew: Jeff Lorsung - 12/23/2024 - C.S. File 67/59-34

Reported as not found.
Looked for with a single GPS tie from the East Center 1/16th. All trees to the north have been logged, no trace of the Hosford I.P.

Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and Jeff Lorsung - 12/17/2025 - C.S. File 67/61-54

Found - ½" Iron pipe leaning approx. 1' south. Returned to plumb position, up 4".
 Metal post 1 ft. south.
New - Sawn - burnt 19"x 1 ft. fir stump S.40°E. 4.4 ft. 3½" mag nail top center.
 Burnt - sawn 12" x 1½ ft. fir stump S.64°W. 8.5 ft. 3½" mag nail right side center.
Notes - Mon in very recent clearcut.
 Area burnt 9/2020.
 Mon on gentle south slope approx. 40 ft. south of a gravel road.
Compass decl. 14¼°E.
TRIMBLE GEO XT POSITION
43.45191053 N. 122.93626834 W.