

TOWNSHIP 24 RANGE 02 POINT IDENTIFIER # 400300

PRIMARY CORNER DESCRIPTION Cor Secs 21, 22, 27, & 28

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619 dated June 5 1893 - (DCSO recs Vol 7 Pgs 2914-5)  
-----  
Set a post, 4 ft. long, 4" sq. 24" in the ground, for cor. to secs. 21, 22, 27, & 28, marked T24S S22 on NE, R2W S27 on SE, S28 on SW, S21 on NW faces, with 2 notches on S & 3 notches on E edges; from which  
A hemlock 24" dia bears N.84°E. 62 lks mkd T24S R2W S22 BT  
A cedar, 24" dia bears S.20°E. 25 lks mkd: T24S R2W S27 BT  
A cedar, 5" dia., bears S.66°30'W., 31 lks., mkd: T24S R2W S28 BT.  
A fir, 60" dia. bears N.35°W. 33 lks. mkd: T24S R2W S21 BT

Douglas Co. Surveyors Office - R.B. Kimberling - P.L. Earle - F.C. Silagy - March 14, 1978 - C.S. File 59/46-75  
-----  
Found - 3" sq. wooden post, not orig.  
24" now 41" Hemlock stump bears N.39°E., (rec. N.84°E.) 40.2 ft. with a well healed blaze.  
24" now 30" Cedar bears S.20°E., 14.6 ft., (rec. 16.5 ft.) with scribing "2W 2" in a partly healed single blaze.  
5" now 16" Cedar bears S.68½°W., (rec. S.66°30'W.) 20.5 ft. with an almost healed single blaze.  
60" now 63" Fir stump bears N.35°W., 21.8 ft. with a well healed single blaze.  
Set - 1"x36" iron pipe with brass cap set 6" above ground  
mkd: DOUGLAS COUNTY SURVEYOR 1978  
T24S R2W  
S 21 | S 22  
S 28 | S 27  
New BTs- 11" Hemlock bears N.84½°E., 40.9 ft., double blazed & marked "T24S R2W S22 CS BT"  
6" Hemlock bears N.14°W., 98.9 ft., double blazed & marked "T24S R2W S21 CS BT"

Robert A. Cook - For: Weyerhaeuser Co. - Dec. 2009 - M160-24  
-----  
Found - 2½" Douglas County 1978 brass cap on 1" pipe up 6" on N. slope about 200 ft. east of a gravel road.  
40" Cedar S.20°E. 14.6 ft. with scribes visible, tag and paint.  
30" Cedar S.68°30'W. 20.5 ft. with healed face, tag and paint.  
24" Hemlock N.84°30'E 40.9 ft. with healed face, tag and paint.

continued next page

1

TOWNSHIP 24 RANGE 02 POINT IDENTIFIER # 400300

PRIMARY CORNER DESCRIPTION Cor. Secs. 21, 22, 27, & 28

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 10/24/2023 - C.S. File 67/57-8

-----  
Found - DCS0 brass cap, up 8" under 40" cedar visible below tree. Cap properly mkd.  
Burned, rotted 40"x 5 ft Hemlock stump N.39°E., 40.2 ft.  
Burned, rotted 54"x 4 ft. fir stump N.34°W., 22.0 ft. (rec. N.35°W., 21.8 ft) add 5/8"x30" iron rod with yellow DCS0 plastic cap driven in top center  
Burned, broken, fallen 40" Cedar S.20°E., 14.6 ft.  
28"x8 ft. cedar S.68°30'W., 20.7 ft. (rec. 20.5 ft) add 3 1/2" mag nail right side center.  
25"x 4 ft. Hemlock stump N.84°30'E., 41.0 ft. (rec 40.9 ft) add 3 1/2" mag nail top center.  
New - 5/8"x30" iron rod up 15" N.86°W., 3.0 ft.  
Note - Area burnt 9/2020  
Compass decl. 14 1/2°E.

Oregon Coordinate Reference System  
Cottage Grove - Canyonville Zone  
N 229840.289 E 270645.855