

TOWNSHIP 24 RANGE 02 POINT IDENTIFIER # 400340

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 21 & 22

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619 dated June 5, 1893 - (DCSO records Vol. 7 Page(s) 2917)

Set a basalt stone 15x12x10" 10" in the ground for ¼ sec. cor. marked ¼ on W face, from which
A cedar, 12" dia., bears N.22°30'E., 12 lks., mkd: ¼ S BT.
A fir, 18" dia., bears N.25°W., 30 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - Aug 1969 - C.S. File 54/27-251

Found - Mound of stones, apparent corner stone, broken, no marks fd.
Orig. 12" now 18" Cedar, alive, N.22½°E., 7.9 ft., now healed blaze. We rescribe "¼ S22 CS BT"
Orig. 18" now 24" Fir, alive, N.25°W., 19.8 ft., shows good scars. We rescribe "¼ S21 CS BT"
Set - Brass cap 12" in ground & built mound of stone around pipe & mkd: County Surveyors Office 1969
T24S ¼ S 21 | S 22 R2W
New BT - 7" Yew S.81°W., 27.3 ft., mkd: "¼ S21 CS BT"
Weyerhaeuser ref-
36" Fir stump S.78°E., 3.0 ft., to "W" nail.
This corner lies on very steep south slope approx. 420 ft N of creek.

Robert A. Cook - For: Weyerhaeuser Co. - Dec. 2009 - M160-24

Found - 1" pipe with 2 3/8" Douglas County 1969 brass cap up 18" on steep south slope. Corner lies about 410 ft north of a creek & 420 ft south of a big cliff
30" D.Fir snag N.25°W., 19.8' with tag.
8" Yew S.81°W., 27.3' with scribes visible.