

TOWNSHIP 24 RANGE 02 POINT IDENTIFIER # 440300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 22 & 27

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619 dated June 5, 1893 - (DCSO records Vol. 7 Page(s) 2915)

Set a basalt stone 15x6x6" 10" in the ground for ¼ sec. cor. marked ¼ on N face, from which

- A hemlock, 36" dia., bears S.58°W., 27 lks., mkd: ¼ S BT.
- A hemlock, 30" dia., bears N.28°E., 8 lks., mkd: ¼ S BT.

V.W. Hosford - Sept. 1957 - C.S. File 42/306-1

Before logging I fd. the marked corner stone & both orig. BTs standing. The BT for sec. 27 was dead.

After logging in both sections, the stone corner is gone, the BT for Sec. 27 is broken off near the ground, the BT for sec. 22 is a burned hollow stump showing old scars, and on the inside, the raised overlay of scribe marks.

From this stump I determined the position of the corner & drove a 1½" iron pipe 36" long, 24" in the ground, from which:

- A Hemlock 11" dia., bears N.78°E., 92.8 ft., mkd: ¼S 22 253 BT.
- A Cedar 36" dia. bears S.19°E., 53.0 ft. mkd: ¼S 27 253 BT

This corner is on a steep hillside sloping north, & 20 ft. west of a small stream flowing NW which is not shown in the orig. notes.