

TOWNSHIP 24 RANGE 02 POINT IDENTIFIER # 440400

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 15 & 22

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

<p>GL0 Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619 dated June 5, 1893 - (DCSO records Vol. 7 Page(s) 2918)</p> <p>-----</p> <p>Set post, 3 ft. long, & 3" sq., 24" in the ground for the 1/4 sec. cor. marked 1/4 S on N face, from which: A vine maple, 6" dia., bears N.5°E., 36 lks., mkd: 1/4 S BT. A vine maple, 6" dia., bears S.82°E., 11 lks., mkd: 1/4 S BT</p>
<p>V.W. Hosford - Sept. 1957 - C.S. File 42/306-4</p> <p>-----</p> <p>After logging in Sec. 22, only one BT remained. The vine maple BT (scribed in bark) for Sec. 22 is in good condition. At the true point of the corner I drove a 2" iron pipe 30" long, 18" in the ground, from which A hemlock 12" dia. bears N.1/2°W. 24.2 ft. mkd: 1/4S 15 253 BT A hemlock 24" dia., bears S.85 1/2°E., 65.2 ft., mkd: 1/4S 22 253 BT.</p>
<p>Glenn McChesney, WEYCO. - 10/23/1957 - C.S. File 53/110-10</p> <p>-----</p> <p>Found - 2" IP 6" Vine Maple, bark scribed - good condition - bears N.5°E., 24 ft. 12" hemlock, N.1/2°W. 24.2 ft. scribed, good condition 24" hemlock, S.85 1/2°E., 65.2 ft., scribed, good condition.</p> <p>New - 48" fir, N.82°E., 37.4 ft., "W" nail & plate. 56" fir, N.20°W., 6.4 ft., "W" nail & plate.</p>
<p>Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - Aug 1969 - C.S. File 54/27-257</p> <p>-----</p> <p>Found - Orig. 6", now 7" vine maple, dead N.5°E., 23.8 ft., bark scribe vis. Do not find IP called for in Hosford ren. due to logging. 12", now 13" hemlock, alive, N.1/2°W., 24.2 ft., good condition, scribe visible on nearly healed blaze. 24" now 24" hemlock, alive S.85 1/2°E., 65.2 ft., scribe visible.</p> <p>Set - Brass cap in cat fire trail mkd: County Surveyors T24S R2W Office 1/4 S 15 1969 S 22</p>
<p>Fd. Ok by BLM C.S. File 63/140-2</p>
<p style="text-align: right;">Cont.</p>

TOWNSHIP 24 RANGE 02 POINT IDENTIFIER # 440400

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 15 & 22

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Daniel Baker - For: Weyerhaeuser Co. - 10/2016 - M172-71

Found - 2½" Douglas Co. brass cap "1969"
Vine maple clump, N.5°E., 23.8' to center per 1894
GLO survey.
64" fir, N.82°E., 38.4' (rec=37.4') Weyerhaeuser BT.
22" rotten hemlock stump, S.85°E., 66.0' to center,
M6-45 BT.
22" rotted hemlock stump, S.85°E., 66.0' to center
M6-45 BT (rec = N.1/2°W., 24.2')(typed as on map)
New - 13" fir, S.22°E., 18.0' to spike side/center -
scribed "¼S22BT"
17" fir, S.78°W., 8.7' to spike side/center -
scribed "¼S15BT"