

TOWNSHIP 24 RANGE 02 POINT IDENTIFIER # 440700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 3; & 34, T23-2

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 5 Page(s) 2173)

Set a Yew post 3 ft. long, 3" sq., 24" in the ground for 1/4 sec. cor. mkd. 1/4 S on N. face, from which
A Fir 40" dia., bears S.10°W., 14 lks. dist. mkd. 1/4 S BT
A Hemlock 18" dia., bears N.20°E., 15 lks. dist. mkd. 1/4 S BT.

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCSO records Vol. 5 Page(s) 2180-81)

(39.00 chs.)
Old 1/4 sec. cor. a post bears South 3.00 chains. I destroyed this post, also the marks on old bearing trees.
(40.00 chs., West)
Set a basalt stone 12x10x6 ins., 8" in the ground for 1/4 sec. cor., marked 1/4 on N. face, from which
A Hemlock 20" dia., bears S.76°30'E., 19 lks. dist. mkd. 1/4 S BT.
A Hemlock 18" dia., bears N.4°W., 8 lks. dist. mkd. 1/4 S BT.

Leonard B. Wilson, Weyerhaeuser Co. - June 3, 1969 - C.S. File 53/106-3

Found - Stone in place.
20" Hemlock, S.76°30'E., 19 lks. (12.5 ft.), scribing visible. Now 30" Hemlock, added "W" nail & plate, S.82°E., 10.6 ft.
18" N.04°W., 8 lks. (5.3 ft.), scribing visible. Now 24" Hemlock snag, added "W" nail & plate, N.05°W., 4.2 ft.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew July 1969 - C.S. File 54/27-164

Found - Corner stone with partial "1/4", "4" chipped off.
20" now 30" Hemlock, alive, S.76 1/2°E., 12.5 ft., shows good scar.
18" now 22" Hemlock, dead, N.4°W., 5.3 ft., scribe visible on unhealed blaze.

Set Brass cap at cor. mkd: County Surveyors Office
(Reset stone alongside) T23S R2W 1/4 S 34
T24S S 3

(Cont. Next Page)

1969

TOWNSHIP 24 RANGE 02 POINT IDENTIFIER # 440700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 3; & 34, T23-2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

New BTs- 8" Hemlock N.22°W., 49.4 ft. mkd. "¼ S34 CS BT".
12" Hemlock S.82°W., 28.1 ft. mkd. "¼ S3 CS BT".
No other trees available.
Brass cap lies toward easterly end of rootwad of NE orig. BT.
Corner lies about 160 ft. West of creek, 2 ft. wide, course SW.

Russell Badgley - For: Weyerhaeuser - 10/2021 - M178-42

Found - A 1½" iron pipe by DCS0 in 1969, firmly set and projecting 4" above the ground, with a 2½" brass cap (properly) marked:
From which BTs by Chandler in 1893 -
A root hole bears N.86°45'E., 12.0 ft (S.76°30'E., 12.5')
A rotten stump bears N.8°30'W., 5.2 FT (N.4°00'W., 5.3')
And BTs by others -
A 18" Hemlock bears N.0°45'W., 32.6 ft w/healed blaze (no record)
New BTs- A 13" Hemlock bears N.37°15'E., 25.0 ft scribed "¼ S34 BT" on double blaze
A 12" Hemlock bears S.36°15'E., 31.2 ft scribed "¼ S4 BT" on double blaze
NAD83 (2011)
LATITUDE 43°31'16.91213"N LONGITUDE 122°55'21.42448"W