

TOWNSHIP 24 RANGE 02 POINT IDENTIFIER # 500440

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 14 & 15, W.C.

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619 dated June 5, 1893 - (DCSO records Vol. 7 Page(s) 2907)

Set post, 3 ft. long, & 3" sq., 24" in the ground for the ¼ sec. cor. marked ¼ S on W face, from which:

- A hemlock, 36" dia., bears S.18°E., 23 lks., mkd: ¼ S BT.
- A hemlock, 6" dia., bears S.55°W., 46 lks., mkd: ¼ S BT.

V.W. Hosford - Sept. 1957 - C.S. File 42/306-5

Before logging both orig. BTs were in good condition. After logging the BT for Sec. 14 is a stump & the BT for Sec. 15 is dead & down.

At the true point of the corner, I drove a 1½" iron pipe 30" long, 18" in the ground, from which:

- A hemlock, 11" dia., bears N.86°E., 53.4 ft., mkd: ¼S 14 253 BT.
- A hemlock, 36" dia., bears S.62°W., 58.1 ft., mkd: ¼S 15 253 BT.

Douglas Co. Surveyors Office - V.R. Tracy - Aug. 18, 1969 - C.S. File 54/27-250

Reported as not found.
Probably destroyed in logging after (1957) ren.

Douglas Co. Surveyors Office - Gary Langlitz, Deputy - Vic Cangie - Mike Tompkins - 1/11/1977 - C.S. File 61/29-41

Referenced out

Found - 1½" IP set along the easterly edge of a fire trail, extending 18" above ground, as set by Hosford. The only remaining orig. BT, an orig. 36" hemlock, now a 38" stump bearing S.18°E., 16.8 ft. (rec. S.18°E., 15.2 ft. measured to face) with scribing "¼S" visible on exposed face.

Trees marked by Hosford:

- An 11" now 12" hemlock with illegible scribing visible on partially healed face, alive & in good condition bears N.86°E., 53.4 ft.
- A 36" hemlock now a 38" snag, with scribing "S 15 253 BT" visible on unhealed blaze bears S.62°W., 59.9 ft. (rec. S.62°W., 58.1 ft.)

Due to future road construction in the area, we reference this corner location as follows:

- A "PK" nail set in the root of a 36" hemlock bears N.17°W., 77.4 ft.

continued next page

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

A "PK" nail set in a notch in the side of a 34" D.Fir stump bears S.23°E., 35.6 ft.
A "PK" nail set in the top of a 58" D.Fir stump bears N.64°W., 37.6 ft.
Compass decl. setting 20° east.

Douglas Co. Surveyors Office - Greg Quibell, Deputy - Debbie Stewart - 12/8/1981 - C.S. File 61/29-41

Found - 1½"x30" I.P. per ren. 1957 lying on top of 58" Fir stump mentioned in (referenced out - 1977) report Orig. 36" now 38" Hemlock stump with scribed "¼S" visible on exposed face. (Rec. per C.S. 59/30 (now C.S. 61/29-41) - S.18°E., 15.2 to face)
12" now 15" Hemlock with illegible scribing visible on partially healed face. (Rec. per C.S. 59/30 (now C.S.61/29-41) - N.86°E., 53.4)
PK nail in notch in the side of 34" fir stump. (Rec. per ref. note S.23°E., 35.6 ft.)
PK nail in top of 58" fir stump. (rec. per ref. notes N.64°W., 37.6 ft)
PK nail in root of 36" Hem. stump. Due to rd const. this tree is no longer vis from cor. location.
38" hem. snag per ref. notes destroyed by rd. conts.

Set - Using PK nail in top of 58" Fir stump, I reset 1½"x30" IP 12" below surface of road in Rd. shoulder. IP bears S.64°E., 37.6 from PK nail. I check this position using PK nail in 34" Fir stump, orig. 38" Hemlock stump & 12" now 15" Hemlock BT. Bearing & dists match record for all three BTs.
Also I set 1"x30" IP with brass cap 50 FT West of ¼ for wit. corner. Brass cap protrudes 10" out of ground, mkd: DOUGLAS CO. SURVEYOR
WIT. COR.
50 FT. EAST TO
¼ S 15 | S 14
T24S R
2
1981 W

New to WC-9" Hemlock scribed "X CS BT" in double blaze bears N.9°W., 45.5.
10" Hemlock scribed ~~X~~ $\frac{CS}{BT}$ in double blaze bears N.1°E., 33.3.
PK nail in 58" Fir stump (Per C.S 59/30, now C.S. 61/29-41) bears N.44°E., 23.5 ft.
Decl. 19°E. See sketch in file.