

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 26 & 35

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

New - 47" fir, S.14½°E., 64.7' 25' tall snag, 1951
9" Hemlock, N.83°W., 24.1', gone 1969
8" Hemlock, N.52°E., 6.4' measured to nail in side center of stump, scribed "S1/4BT"
8" D.Fir, N.6°E., 15.0' measured to nail in side center of stump, scribed "S1/4BT"
7" D.Fir, N.31°W., 9.6' measured to nail in side center of stump, scribed "S1/4BT"
7" Hemlock, S.52°E., 31.1' measured to nail in side center of stump, scribed "S1/4BT"

Fd Ok by R Quimby 10/2020 - C.S. File 65/106-51

Douglas Co. Surveyors Office - Crew: Stephen Flauser & Jeff Lorsung- 10/18/2023 - C.S. File 67/57-5

Found - BLM brass cap, up 6"
Root hole, N.42°E., 67.2 ft.
Burned, broken off, 45"x20 ft. fir snag, S.14½°E., 64.7 ft.
10" hemlock, N.52°E., 6.4 ft., nail in side center.
Sawn 8"x2½ ft. fir stump, N.11°E., 15.2 ft. (rec. N.6°E., 15.0) add 3½" mag nail top center.
10" D.Fir N.26½°W., 9.6 ft. (Rec. N.31°W.) dist to nail side center.
Down, 8" Hemlock, S.52°E., 31.1 ft. dist to roots, vis scribes on partially healed single blaze.
New - 5" hemlock, scribed "X" "BT" on high, low blaze bears S.40°W., 3.6 ft.
Note - Mon on moderate north slope, old growth forest to south, clear cut to north.
Area burnt 9/2020
Compass decl. 14½°E.
Oregon Coordinate Reference System
Cottage Grove - Canyonville Zone
N 224724.376 E 278548.007

Douglas Co. Surveyor's Office - Crew: Stephen J. Flauser and Jeff Lorsung - 1/6/2026 - C.S. File 67/61-59

Found - 1951 BLM brass cap proj. 6".

S 26
¼ S 35
1951

Continued next page

TOWNSHIP 24 RANGE 02 POINT IDENTIFIER # 540200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 26 & 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Burnt - rotted 44" fir S.14½°E. 64.7 ft. 20' tall snag. Fully healed single blaze.
10" Hemlock N.52°E. 6.4 ft. partly healed single blaze scribe visible.
Sawn 10" x 3 ft. D. Fir stump N.10°E. 15.1 ft. (Rec N.6°E. 15.0 ft.) nail top center.
11" D. Fir N.31°W. 9.7 ft. (Rec 9.6 ft.) fully healed single blaze.
9" Hemlock fallen out of position. No good root hole. Partly healed single blaze, scribes visible
Metal posts S.45°E. 1.6 ft. and N.70°W. 1.0 ft.
All trees are side spiked.

New - 5" Hemlock high low blaze marked X BT S.40°W. 3.4 ft
3½" mag nail, right side center.

Notes - Mon. approx. 90 ft. South of gravel road.
Area burnt 9/2020
Mon on moderate North slope. Old growth forest South
Large clearcut to North.

Compass decl. 14¼°E.
TRIMBLE GEO XT POSITION
43.44904891 N.
122.90209980 W.