

TOWNSHIP 24 RANGE 02 POINT IDENTIFIER # 600400

PRIMARY CORNER DESCRIPTION Cor. Secs. 13, 14, 23, & 24

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619 dated June 5, 1893 - (DCSO records Vol. 7 Page(s) 2895)

-----  
Set a basalt stone 20x18x12" 15" in the ground for the cor. to secs. 13, 14, 23, & 24, marked with 3 notches on S & 1 notch on E edges, from which  
A hemlock, 6" dia., bears N.75°E., 30 lks., mkd: T24S R2W S13 BT.  
A yew, 10" dia. bears S.35°E., 28 lks mkd: T24S R2W S24 BT  
A fir, 20" dia. bears S.22°W., 5 lks. mkd: T24S R2W S23 BT  
A fir, 16" dia. bears N.55°W., 19 lks mkd: T24S R2W S14 BT

Bruce Shaner - For: Evans Products Co. - Nov. 1962 - C.S. File 51/245

-----  
Found - Orig. basalt stone from which a:  
14" Hemlock, scribes visible, tree now blown down, bears NE.  
30" D.Fir bears S.22°W., 3.3 ft., with old face.  
16" D.Fir a snag now with old face, bears N.55°W., 12.5 ft.  
I restored above corner by setting a 1"x36" galv. iron pipe, from which:  
26" D.Fir bears N.45°W., 23.2 ft., scribed "S14 BT"  
38" D.Fir bears N.14°E., 11.4 ft., scribed "S13 BT"  
8" Yew bears S.25°E., 46.6 ft., scribed "S24 BT"

Ron Quimby - Crew: N. Fromdahl & R. Olsen - 6/2014 - C.S. File 65/82-43

-----  
Found - 1" iron pipe.  
44" fir N.14°E., 11.4 ft. good scar.  
32" Fir N.45°W., 23.2 ft. good scar.  
46" Fir S.22°W., 7.0 ft. (rec. 3.3) good scar. Tree is leaning badly.  
New BT - 12" Fir S.17°E., 23.3 ft. scribed T24S R2W S24 BT. Compass decl. 15½°E.