

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 12 & 13

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619 dated June 5, 1893 - (DCSO records Vol. 7 Page(s) 2898)

-----

Set a basalt stone 18x10x8" 12" in the ground for ¼ sec. cor. marked ¼ on N face, from which

A fir, 24" dia., bears N.75°W., 40 lks., mkd: ¼ S BT.

A fir, 14" dia., bears S.11°W., 29 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - July 1970 - C.S. File 54/27-234

-----

Found - No trace of corner stone.

Orig. 14" now 20" Fir, alive, S.11°W., 19.1 ft., we open & find scribe.

Orig. 24" now 28" Fir, alive, N.75°W., 26.4 ft., shows good scar, we tag.

Set - Brass cap at cor. mkd: County Surveyors T24S R2W  
Office  
1970
¼
S 12  
S 13

New BTs- 10" Cedar N.63°E., 5.6 ft., mkd: "¼ S12 CS BT"

14" D.Fir S.35°E., 31.1 ft., mkd: "¼ S13 CS BT"

This corner lies on very steep SW slope of mountain about 650 ft. west of top.

BLM Dependent resurvey by Dale Bedell, Cadastral Surveyor, under Group #1533, surveyed May. 1990 - (DCSO records Vol. 50 Page(s) 18997-8)

-----

The ¼ sec cor. of secs. 12 & 13, perpetuated by Tracy, in 1970, monumented with an iron post, 1½" dia., firmly set, projecting 12" above ground, with brass cap mkd.

COUNTY SURVEYORS OFFICE

T 24 S

¼ S 12

S 13

R 2 W

1970

from which the original bearing trees

A fir, 21" dia., bears S.11°W., 29 lks., with illegible scribe marks on a partially opened blaze.

A fir, 29" dia., bears N.69°W., 40 lks., with healed blaze. (Record, N.75°W.)

and the remains of the bearing trees mkd. by Tracy

A root hole, bears N.63°E., 8 lks., with a down cedar alongside, 12" diam., with healed blaze.

A fir, 17" dia., bears S.35°E., 47 lks. with healed blaze.