

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 - (DCSO records Vol. 5 Page(s) 2171)

Set a Yew post 3 ft. long, 3' sq., 24" in the ground for ¼ sec. corner, mkd. ¼ S. on N. face, from which
A W.Fir 6" dia., bears N.21°E., 12 lks. dist. mkd. ¼ S BT.
A Red Fir 30" dia., bears S.10°W., 13 lks. dist. mkd. ¼ S BT.

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCSO records Vol. 5 Page(s) 2178)

(39.50 chs.)
The old ¼ sec. cor., a post bears South 23 lks. dist. I destroyed this post and also the marks on the old bearing trees.
(40.00 chs., West)
Set a stone 20x12x7 ins., 15" in the ground for ¼ sec. cor. mkd. with ¼ on N. face, from which
A Hemlock 12" dia., bears N.64°W., 10 lks. dist. mkd. ¼ S BT.
A Hemlock 10" dia., bears S.6°W., 25 lks. dist. mkd. ¼ S BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew July 3, 1969 - C.S. File 54/27-157

Found - Stone 20"x12"x7", mkd. "¼", tipped out.
Orig. 12" now 13" Hemlock, alive, N.64°W., 6.6 ft., scribe visible on nearly healed blaze. Rescribed "¼ S36 CS BT".
Orig. 10" now 11" Hemlock, alive, S.6°W., 16.5 ft., scribe visible on previously opened blaze. Rescribed "¼ S1 CS BT".
Set Brass cap at cor. mkd: County Surveyors Office
(Reset old corner stone T 23 S R2W ¼ S 36
alongside) T 24 S R2W ¼ S 1
1969
Corner lies 15 ft. South and 30 ft. East of small creek, flowing SW.

(Cont. Next Page)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Weyerhaeuser Co. - 1966-1981 - C.S. File 58/8-4

Weyerhaeuser Co. survey record of Oct. 20, 1966 by McChesney and H.E. Case, found of the 1894 GLO accessories:

Stone found.

12" Hemlock, N.64°W., 10 lks.; 6.6 ft., found a 10" Hemlock, scribing visible, N.67°W., 4.8 ft. to face.

10" Hemlock S.6°W., 25 lks.; 16.5 ft., found a 9" Hemlock, scribing visible, S.6°E., (rec. S.6°W) 17.5 ft.

Referenced stone as corner point with "W" nails and plates on:

36" Fir N.77°W., 6.1 ft.

38" Fir S.3°E., 12.6 ft.

Weyerhaeuser Co. field check by McChesney Oct. 19, 1969 found DCSO brass cap with original stone alongside, the brass cap 2 ft. East of the stone location in 1966. Observed original Hemlock BTs were rescribed. Removed 1966 W. Co. plates and re-referenced same trees & W nails with new bearings and distances:

36" Fir N.73°W., 7.6 ft.

38" Fir S.3°W., 11.7 ft.

On Feb. 18, 1981, I did not find the brass cap or the original stone. The corner point fell under a large imbedded Fir slab. Hemlock BTs OK. W. Co. reference to SW. OK, but the W. Co. NW. reference now a stump with "W" nail and plate both removed by logging.

Douglas County Surveyors Office - Gregory Quibell, Deputy - Debbie Stewart, Witness - Sept. 9, 1981 - C.S. File 61/27-38

Found - Brass cap buried under several large logs. After removing the logs, I find the BC firmly set, protruding 1" above the ground, properly marked.

13" Hemlock, orig. BT, alive, bears N.66½°W., 6.5 ft. (Rec. N.64°W., 6.6 ft.) with scribed "S36 CS BT" visible in unhealed blaze.

12" Hemlock (Orig. 10"), alive, bears S.8°W., 16.5 ft. (Rec. S.6°W.) with scribed "S1 CS BT" visible on unhealed blaze.

"W" nail in base of 38" Fir snag, 17 ft. tall, (CS 58/8), bears S.3°W., 11.6 ft. Also found a cruiser mark cut deeply in bark.