

PRIMARY CORNER DESCRIPTION W. 1/4 Cor. Sec. 19 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM Resurvey by Norman D. Price, Cadastral Engineer, under Group #242, Surveyed June/Aug. 1950 - (DCSO records Vol. 27 Page(s) 11465)

Point for the ¼ sec. cor. of sec. 19, T24S R3W., at midpoint on the W. bdy. of sec. 19.
Set an iron post 3 ft. long, 1" dia., 28" in the ground with brass cap mkd. ¼ S 19
1950

from which
A Fir 32" dia., bears N.64½°E., 30 lks. dist. mkd. ¼ S19 BT.
A Cedar 13" dia., bears S.84½°E., 90 lks. dist. mkd. ¼ S19 BT.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Vernon Tracy; M. Stone - June 13, 1963 - C.S. File 53/9-101

Found - GLO brass cap set in 1950.
13" Red Cedar S.84½°E., 59.4 ft., alive and in good condition, shows scar.
Sawed stump of 32" Fir N.64½°E., 19.8 ft., face still on stump.
New BT - 12" Hemlock N.77½°E., 55.3 ft. mkd. ¼ S19 CS BT.

Douglas Co. Surveyors Office - L.E. Monrean, Deputy - T. Plouff, witness - Nov. 17, 1981 - C.S. File 61/29-29

Found - BLM brass cap properly stamped, protruding 3" above ground.
32" Fir bears N.64½°E., 19.8 ft. with "¼ S19" visible on partially healed blaze. Now a stump.
13" now 24" Cedar bears S.83°E., 59.4 ft. (Rec. S.84½°E.) with a well healed single blaze.
12" Hemlock now 16", bears N.77½°E., 55.3 ft. "S19 CS B" visible on a partially healed single blaze.
New BTs- 9" Cedar bears N.33½°E., 39.5 ft. scribed "¼ S19 CS BT" on a double blaze.
14" Maple bears S.21°E., 46.4 ft. scribed "¼ S19 CS BT" on a double blaze. (Maple tree is on the corner of a cutting line.)