

PRIMARY CORNER DESCRIPTION NE 1/16 sec. 31

Alias	Description

BLM dependent resurvey by Wm. W. Glenn, Cadastral Surveyor, under Group #416, surveyed Sept/Oct 1958 - (DCSO records Vol. 30 Page(s) 12602)

Point for the NE 1/16 sec. cor. of sec. 31, at intersection with the E & W center line of the NE¼.
Set an iron post, 28" long, 2½" dia., 26" in the ground, with brass cap marked:

NE 1/16 S31

1958

from which

- A fir, 8" dia. bears S.32½°E. 138 lks. mkd: NE 1/16 S31 BT
- A fir, 40" dia bears N.40°W. 118½ lks. mkd: NE 1/16 S31 BT

Douglas Co. Surveyor's Office - Crew: Stephen Flause & Mike Koch - 5/11/2016 - C.S. File 67/44-12

Found - A 2½" dia. Iron post by Glenn, 1958 USBLM, projecting 10" above a road fill bank and leaning westerly approximately 4" at the top, with a 3 1/4" brass cap (properly) mkd.

BTs by Glenn in 1958 -

- A 25" dia. x 6' tall d. fir stump bears S.32½°E., 91.1 ft. With a healed single blaze.
- A root hole bears N.40°W., 78.2 ft. with an uprooted 42" dia. D.Fir laying alongside with scribe marks "NE 1/16 S31 BT" visible on a partially healed single blaze.

New - The 1958 USBLM monument is reset in a plumb position which matches the original bearing and distance to the found 1958 BT ("RESET 2016" add to cap)

- A 14" dia. Maple bears N.37½°E., 8.8 ft. scribed "NE 1/16 S31 CS BT".
- A 23" dia. D.Fir bears S.02½°W., 17.0 ft. scribed "NE 1/16 S31 CS BT".

Location & comments - All BTs have BT tags attached. All new BTs have double blazed faces with bearings measured to the center of the tree at the root crown and distances measured to the side and center of the root crown.

The corner falls in the westerly fill bank and approximately S.45°W., 35 ft. From the centerline of a rocked forest access road and approximately N.45°E., 80 ft. from a stream, course SE. The SE quadrant is mostly a clearcut unit & the NE, NW & SW quadrants are forested with older growth fir timber.

Compass declination - 15°E.