

TOWNSHIP 24 RANGE 03 POINT IDENTIFIER # 240200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 29 & 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars under contract #152, dated June 3, 1871 - (DCSO records Vol. 7 Page(s) 2957)

Set ¼ sec. post from which
A fir, 6" dia., bears N.30°E., 22 lks.
A fir, 5" dia., bears S.45°E., 11 lks.

Douglas Co. Surveyors Office - James W. Byron, Deputy -
Witnesses: G. Welker & J. Fee - For: Roseburg Lumber Co. -
Oct. 29, 1956 - C.S. File 47/132

BTs not found. Position of corner determined by using Roberts
dist. from midpoint of N S center line Sec. 29 & call to rock
bluff (as called for in Gov. line notes).

See (Field) book 7 page 7 for Roberts survey. (Runs the N-S
centerline of sec. 29 & checks into S ¼ Sec. 29. 1/29/2004
DCSO)

Set brass cap at corner mkd: ¼ S29/S32 T24S R3W County
Surveyors Office 1956 from which:

A 39" Fir stump 42" high bears S.16°W., 47.0 ft. scribed
¼ S32 CS BT.

No other good stumps or trees within 500 ft. of this
corner.

Daniel Baker - Weyerhaeuser Co. - 12/15/94 - M 121-58 A&B

Found - Douglas county brass cap dated 1956
39" rotten stump, S.16°W. 47', visible scribing,
rec. S.16°W. 47' - 1956 Do. Co.

New BTs- 14" fir, N.53°E. 23.1' - scribed "¼ S29 BT"
7" fir, S.63°E 4.4' - scribed "¼ S32 BT"
12" fir, S.31°W. 8' - scribed "¼ S32 BT"
9" fir, N.13°W. 27.1' - scribed "¼ S29 BT"
6' Fencepost 1' north.

FD. Ok by D. Edwards, Oct. 2002 - M137-52