

TOWNSHIP 24 RANGE 03 POINT IDENTIFIER # 300100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 32 & 33; 4 & 5 of T25-3

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - W.H. Byars, Under Contract #152 dated June 3, 1871
(DCSO records, Volume 7 Page 2944)

Set post cor. to secs. 5, 4, 32 and 33, from which
A Cedar 16" dia. bears N.60°E., 13 lks. dist.
A Cedar 24" dia. bears S.60°E., 9 lks. dist.
A Cedar 12" dia. bears S.80°W., 17 lks. dist.
A Fir 16" dia. bears N.75°W., 19 lks. dist.

A. Boyer, Deputy Co. Surveyor - For Roseburg Lumber - June,
1939 - C.S. File 35/38 and C.S. File 16/29

Renewed from original BTs:

A 16" Fir N.75°W., 19 lks.
A 24" Cedar S.60°E., 9 lks.

Set 4" x 4" Fir post for corner from which new BTs:

A 40" Cedar bears N.10°E., 26.0 ft. marked S33 T24S R3W
CS BT.
A 15" hemlock bears S.58°W., 17.0 ft. marked S5 T24S R3W
CS BT.

GL0 Dependent Resurvey by Norman D. Price Under Special
Instructions dated April, 1940 (DCSO records, Vol. 27 Pgs
11533-34)

The original cor. of secs. 4, 5, 32 and 33, the locus of which
has been perpetuated by the county surveyor's Fir stake, 4 ft.
long, 4" sq., firmly set, mkd. S33 on NE., S4 on SE., S5 on
SW., and S32 on NW. face. At point for corner,
Set an iron post, 3 ft. long, 2" dia., 28" in the ground, with
the county surveyor's marked stake deposited at the base, for
cor., with brass cap mkd:

T24S R3W
S32|S33

S5|S4
T25S
1944

from which
A Cedar 38" dia. bears S.72°E., 13 lks. dist., with blaze
healed. (Old BT)
A Fir 30" dia. bears N.70½°W., 21 lks. dist., with blaze
healed. (Old BT).
A Cedar 42" dia. bears N.10½°E., 44 lks. dist., mkd. S33
T24S R3W CS BT (Co. Surveyors tree)

(Cont. Next Page)

TOWNSHIP 24 RANGE 03 POINT IDENTIFIER # 300100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 32, 33; & 4, 5 of T25-3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A Hemlock 24" dia. bears S.61°W., 30 lks.dist., mkd. S5
T25S R3W CS BT. (Co. Surveyors tree)
This sec. cor. is located at the NE cor. of a logged over
area.

James W. Byron, Deputy Co. Surveyor - Milo Godfrey; Clete
Putnam - March 24, 1960 C.S. File 49/78-1

Found - Scribe stake & steel fence post at corner.
Brass cap, out of position & covered by downfall.
I reset brass cap at corner and scribe new BTs. All existing
BTs are now downfalls. All check record.
New BTs - 11" W.Fir bears N.45½°E., 19.7 ft. scribed S33 T24S
R3W CS BT.
14" R.Cedar bears S.61½°E., 30.3 ft. scribed S4
T25S R3W CS BT.
7" W.Fir bears S.26°W., 6.0 ft. scribed S5 T25S
R3W CS BT.
5" Cedar bears N.36°W., 27.5 ft. scribed S32 CSBT.